

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000115/KQY3N2**Date:** 08/02/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00067492101	
Claimant Vehicle No :	SFN686B	Insured Vehicle No :	GBJ5882L	
Date of Loss:	03/01/2022	Nature of Claim:	TP	Claim No: SNM22D200064/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFN686B		Engine No:	G4FGHU837205
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)		Chassis No:	KMHD841CMJU593443
Reg. Date:	09/12/2017 (Man. Year: 2017)		Odometer:	140327 km
Colour:	Metallic Blue			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,951.60	3,077.72	10,873.88	77.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	1,620.00	2,880.00	64.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	18,451.60	4,697.72	13,753.88	74.54
+ GST 7.00/7.00% (\$\$)	1,291.61	328.84	962.77	74.54
Nett Amount (\$\$)	19,743.21	5,026.56	14,716.65	74.54

INSPECTION

Date of Assignment:	05/01/2022	Accord Auto Services Pte Ltd (HQ)
Date Inspected:	12/01/2022 Inspected At:	10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Estimated Period of Repair:	6.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFN686B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Serviceable	1,198.00 FL	*- FL
2	1		*FRONT HEADLAMP RH	Serviceable	1,198.00 FL	*- FL
3	2		*FRONT HEADLAMP LOWER BRACKET	Repair	48.00 FL	*- FL
4	1		*FRONT BUMPER	Buckled/Cracked	474.40 FL	*474.40 FL
5	1		*FRONT BUMPER SPONGE	Cracked	90.00 FL	*90.00 FL
6	1		*FRONT BUMPER RUBBER TOP	Serviceable	150.00 FL	*- FL
7	1		*FRONT GRILLE BASE	Cracked	320.00 FL	*320.00 FL
8	1		*FRONT GRILLE EMBLEM	Necessary	100.00 FL	*100.00 FL
9	10		*FRONT GRILLE CHROME MOULDING	Serviceable	250.00 FL	*- FL
10	1		*FRONT NUMBER PLATE GARNISH	Cracked	27.00 FL	*27.00 FL
11	1		*FRONT BUMPER LOWER	Serviceable	55.00 FL	*- FL
12	1		*TOWING COVER	Serviceable	16.00 FL	*- FL
13	2		*LH & RH FOGLAMP	Serviceable	530.20 FL	*- FL
14	2		*FRONT FOGLAMP GARNISH	Serviceable	230.80 FL	*- FL
15	1		*FRONT LH FENDER	Repair	1,227.00 FL	*- FL
16	1		*FRONT RH FENDER	Repair	1,227.00 FL	*- FL
17	1		*BONNET	Repair	1,910.30 FL	*- FL
18	2		*BONNET HINGE	Repair	129.60 FL	*- FL
19	1		*FRONT SUPPORT PANEL	Serviceable	949.30 FL	*- FL
20	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	74.10 FL	*- FL
21	1		*REINFORCEMENT BAR	Repair	695.50 FL	*- FL
22	2		*RADIATOR AIR DUCT LH & RH	Serviceable	77.40 FL	*- FL
23	1		*REAR BOOT	Bent	1,782.00 FL	*1,782.00 FL
24	2		*REAR BOOT HINGE	Repair	144.00 FL	*- FL
25	1		*REAR BOOT LOGO	Necessary	32.00 FL	*32.00 FL
26	1		*REAR BOOT LOGO ELANTRA	Necessary	48.80 FL	*48.80 FL
27	1		*REAR BOOT LOGO S	Necessary	50.00 FL	*50.00 FL
28	1		*REAR BOOT OPEN HANDLE OPEN SWITCH	Serviceable	150.00 FL	*- FL
29	1		*REAR BOOT LICENCE PLATE LIGHT	Serviceable	30.00 FL	*- FL
30	2		*REAR BOOT LAMP LH & RH	Serviceable	569.80 FL	*- FL
31	1		*REAR BOOT LOCK	Repair	116.20 FL	*- FL
32	1		*REAR BOOT RUBBER	Serviceable	92.50 FL	*- FL
33	2		*REAR LAMP LH & RH	Serviceable	725.20 FL	*- FL
34	1		*REAR BUMPER	Bent	459.40 FL	*459.40 FL
35	2		*REAR BUMPER SIDE RETAINER SHORT	Serviceable	88.60 FL	*- FL
36	1		*REAR BUMPER LOWER	Serviceable	250.10 FL	*- FL
37	2		*REAR BUMPER REFLECTOR LH & RH	Serviceable	81.60 FL	*- FL
38	1		*REAR END PANEL	Repair	454.60 FL	*- FL
39	1		*REAR END PANEL TOP GARNISH	Serviceable	59.80 FL	*- FL
40	1		*REAR REINFORCEMENT	Bent	294.80 FL	*294.80 FL
41	1		*REAR FLOOR PANEL	Repair	120.00 FL	*- FL
42	1		*FRONT & REAR NUMBER PLATE WITH HOLDER (2 Pcs)	Frt Bent	100.00 FS	*45.00 FS
43	2		*SET FRONT & REAR BUMPER CLIPS	Necessary	90.00 FS	*90.00 FS
44	1		*SET SUPPORT PANEL TOP COVER CLIPS	Not Necessary	50.00 FS	*- FS
45	2		*SET FRONT & REAR FENDER SHIELD CLIPS	Not Necessary	140.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*SET REVERSE SENSOR	Serviceable	350.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,257.00	3,813.40
- List Item Discount on L Items 20.00/20.00% (\$\$)					3,305.40	735.68
Total Parts (\$\$)					13,951.60	3,077.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ALL AFFECTED AREA (FRONT & REAR)	New	1,800.00	800.00
2	LABOUR REMOVE/REFIT ACCIDENT DAMAGES PARTS TO STRAIGHTEN UP,JACK OUT,CUT/WELD AND REALIGN ACCIDENT AFFECTED AREAS	New	1,600.00	700.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	40.00
4	TO REMOVE/REPLACE/REFIX AIRCON CONDENSOR,RADIATOR NECESSARY PIPING,HOSE,TOP UP AIRCON GAS,COOLANT & ETC	New	200.00	0.00
5	TO REMOVE/REPLACE/REFIX SUPPORT PANEL	New	280.00	0.00
6	TO REMOVE/REFIX/REPLACE REVERSE SENSOR	New	180.00	50.00
7	TO REMOVE/REFIX REAR BOOT COMPARTMENT,MECHANISM TO NEW BOOT	New	180.00	0.00
8	ANTI RUSH TREATMENT	New	160.00	30.00
Gross Labour Cost (\$\$)			4,500.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >