



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 7965A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	633.00	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	45.00	-
1	HEADLAMP LH	SERVICEABLE	1,680.00	-
1	HEADLAMP BRACKET LH	SERVICEABLE	84.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,234.20	-
1	FRONT DOOR OUTER MOULDING RH	SERVICEABLE	175.40	-
1	FRONT DOOR OUTER CHROME HANDLE LH	CUT	250.10	189.10
1	FRONT DOOR FRAME STICKER LH	NOT NECESSARY	70.00	-
1	LH WING MIRROR ASSY	CRACKED	821.10	751.20
1	FRONT DOOR GLASS LH	SERVICEABLE	675.00	-
1	FRONT DOOR REGULATOR MOTOR LH	SERVICEABLE	396.00	-
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,193.10	-
1	REAR DOOR HANDLE OUTER CHROME HANDLE	SERVICEABLE	250.10	-
1	REAR DOOR FRAME STICKER LH	NOT NECESSARY	70.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	608.90	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	45.00	-
1	TAILLAMP LH	SERVICEABLE	632.50	-
	LESS 20% DISCOUNT		-	-188.06
			8,863.40	752.24
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT DOOR TRIMBOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR TRIMBOARD CLIPS (SN)	NOT NECESSARY	50.00	-
			200.00	-

Report Ref No. CS/SMR22000123/Kqf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	STRAIGHTEN & PANEL BEAT ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT DOOR LH, REAR DOOR LH AND REAR BUMPER.		1,200.00	400.00
	SPRAY PAINTING ON ACCIDENT AREAS.		1,400.00	1,000.00
	CHECK & REPAIR WIRING SYSTEM.		120.00	15.00
	R&R FRONT DOOR COMPONENTS.	NOT NECESSARY	120.00	-
	R&R REAR DOOR COMPONENTS.	NOT NECESSARY	120.00	-
	RESPRAY TUFF KOTE ON ACCIDENT AREA.	NOT NECESSARY	120.00	-
			3,080.00	1,415.00
	<b>GRAND TOTAL</b>		<b>12,143.40</b>	<b>2,167.24</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,700.00</b>

Report Ref No. CS/SMR22000123/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.