2/23/22, 4:01 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III22000126/GQF3N2

23/02/2022 Date:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

**Claimant Vehicle** SMD4036X Insured Vehicle No: SLL8290X No:

Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: MFL2022D0000072

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMD4036X

Make & Model: TOYOTA PRIUS, 1.5 (A) 2ZR8379877 **Engine No:** Reg. Date: 17/08/2018 (Man. Year: 2018) Chassis No: ZVW516064647 Colour: Odometer: 135889 km White

**Engine Capacity:** 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: CST 6 mm Rear Left Side: CST 6 mm CST 6 mm Front Right Side: CST 6 mm Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,063.50	901.87	1,161.63	56.29
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,410.00	400.00	1,010.00	71.63
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,473.50	1,301.87	2,171.63	62.52
	Approved Total (Overridden) (S\$)		1,050.00		
	Nett Amount (S\$)	3,473.50	1,050.00	2,423.50	69.77

**INSPECTION** 

Date Inspected:

05/01/2022 Date of Assignment:

BLK 5035 ANG MO KIO INDUSTRIAL PARK 2

#01-357

10/01/2022 Inspected At: SINGAPORE 569538

REPAIRER:T & S MOTOR SERVICE

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Feb 2022)

Parts: TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD4036X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	485.60 F	*485.60 FL
2	1		*REAR BUMPER LOWER SPOILER	Cut	326.40 F	*326.40 FL
3	1		*REAR BUMPER LH LAMP	Not Necessary	286.20 F	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	156.00 F	*- FL
5	1		*REAR BUMPER INNER REINFORCEMENT	Bent	519.30 F	*350.50 FL
6	1		*SET FRONT BUMPER CLIP	Necessary	40.00 F	*40.00 FL
7	1		*SET REVERSE SENSOR	Not Necessary	250.00 F	*- FL
F=Fra	anchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	2,063.50	1,202.50
			- List Item Discount on	L Items 0.00/25.00% (S\$)	0.00	300.63
				Total Parts (S\$)	2,063.50	901.87
			Report was unsubmitted during	n this print-out		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	LABOUR CHARGE FOR REMOVE, PANEL BEAT, WELDING, ALIGN AND RENEW REPLACED PARTS	New	700.00	200.00
2	SPRAY PAINTING ON REAR BUMPER AND ACCIDENT AFFECTED AREAS	New	600.00	200.00
3	TO CHECK WIRING AND LIGHTINGS	New	50.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	60.00	0.00
	Gross Labour	Cost (S\$)	1,410.00	400.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >