

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000127/AVY3E2

Date: 13/05/2022

REFERENCE

Insured/Claimant:	DENNIS BELING	Policy No:	2070126304		
Date of Loss:	09/11/2021	Nature of Claim:	OD	Claim No:	0124147020SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU7868C		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD897587
Reg. Date:	28/08/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF3XL1116157
Colour:	Grey	Odometer:	10422 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,831.00	4,453.28	5,377.72	54.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,032.00	4,012.00	3,020.00	42.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,863.00	8,465.28	8,397.72	49.80
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	16,063.00	7,665.28	8,397.72	52.28
+ GST 7.00/7.00% (S\$)	1,124.41	536.57	587.84	52.28
Nett Amount (S\$)	17,187.41	8,201.85	8,985.56	52.28

INSPECTION

Date of Assignment:	05/01/2022		
Date Inspected:	16/11/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,634.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	211.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	459.00 FS	*367.20 FS
4	1		*REAR LIGHT REFLECTOR - RH	Not Necessary	41.00 FS	*- FS
5	1		*LED TAIL LIGHT - RH	Not Necessary	926.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	63.00 FS	*- FS
7	2		*REAR WHEEL ARCH COVER - LH / RH	N/S Necessary / O/S Cut	536.00 FS	*428.80 FS
8	1		*REAR DOOR - RH	Dented	2,909.00 FS	*2,327.20 FS
9	1		*REAR OUTER DOOR SEAL - RH	Necessary	135.00 FS	*108.00 FS
10	1		*REAR DOOR CATCH - RH	Not Necessary	120.00 FS	*- FS
11	1		*REAR DOOR HANDLE, EXTERIOR - RH	Repair	198.00 FS	*- FS
12	1		*REAR DOOR HANDLE CAP - RH	Not Necessary	27.00 FS	*- FS
13	1		*REAR DOOR COVER - RH	Necessary	257.00 FS	*205.20 FS
14	1		*REAR ALUMINIUM RIM - RH	Cut	1,262.00 FS	*1,009.60 FS
15	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	241.00 FS	*- FS
16	1		*REAR UNDERBODY TRIM - RH	Not Necessary	52.00 FS	*- FS
17	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
18	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
19	1		*SUNDRIES	Necessary	300.00 FS	*7.28 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 9,831.00 4,453.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER MODULE DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
4	TO RESPRAY REAR BUMPER, RHS REAR FENDER AND RHS REAR DOOR	New	3,000.00	1,650.00
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,032.00	4,012.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >