

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22000129/RPA3Q2**Date:** 23/09/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MCV0001490_03

Claimant Vehicle No : SMW6973C **Insured Vehicle No :** GX7505E

Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: MCV2022D0000126

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW6973C**

Make & Model: MAZDA 6, 2.0 STANDARD I4 (A) Engine No: PE21355396

Reg. Date: 01/12/2020 (Man. Year: 2019) Chassis No: JM6GL1073L0405846

Colour: Blue Odometer: 9208 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,440.70	1,426.00	1,014.70	41.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	2,140.00	1,740.00	44.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,320.70	3,566.00	2,754.70	43.58
+ GST 7.00/7.00% (S\$)	442.45	249.62	192.83	43.58
Nett Amount (S\$)	6,763.15	3,815.62	2,947.53	43.58
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		4,115.62		

INSPECTION

Date of Assignment: 05/01/2022

Date Inspected: 07/01/2022 Inspected At:

Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2022)
Parts:	143	MAZDA 6 2.0 STANDARD I4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW6973C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,154.80 F	*1,154.80 F
2	4		*TAPE,PROTECTOR	Necessary	18.80 F	*18.80 F
3	2		*RETAINER S.S ULTRASONIC CENTER	Not Necessary	36.40 F	*- F
4	2		*SENSOR ULTRASONIC CENTER	Not Necessary	363.40 F	*- F
5	1		*BRACKET CENTER REAR BUMPER	Not Necessary	5.40 F	*- F
6	1		*REINFORCEMENT REAR	Not Necessary	538.30 F	*- F
7	2		*TAPE SEAL	Necessary	27.40 F	*27.40 F
8	1		*COVER TOWING RH REAR	Missing	46.60 F	*46.60 F
9	1		*REFLECTOR RH	Not Necessary	41.20 F	*- F
10	2		*RIVET	Necessary	18.40 F	*18.40 F
11	6		*FASTENER	Necessary	48.00 F	*48.00 F
12	1		*FASKET TAIL LAMP RH	Necessary	46.00 F	*46.00 F
13	1		*FASKET TAIL LAMP LH	Necessary	46.00 F	*46.00 F
14	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,440.70	1,426.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS	New	1,320.00	660.00
2	TO RESPRAY REAR BUMPER AND ALL AREAS AFFECTED BY THE ACCIDENTS	New	1,260.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	660.00	330.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	180.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	250.00
6	APPLY CERAMIC COATING ON THE AFFECTED AREA ,REAR BUMPER	New	90.00	90.00
Gross Labour Cost (\$\$)			3,880.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >