

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22000131/KEA3Q2**Date:** 05/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100416488
Claimant Vehicle No :	SCZ262M	Insured Vehicle No :	SKT4709C
Date of Loss:	03/01/2022	Nature of Claim:	TP
		Claim No:	2303220477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCZ262M	Engine No:	L15B4420828
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11220826
Reg. Date:	05/07/2017 (Man. Year: 2017)	Odometer:	66889 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,749.56	1,438.56	1,311.00	47.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,060.00	690.00	39.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,499.56	2,498.56	2,001.00	44.47
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	4,499.56	1,950.00	2,549.56	56.66
+ GST 7.00/7.00% (S\$)	314.97	136.50	178.47	56.66
Nett Amount (S\$)	4,814.53	2,086.50	2,728.03	56.66
+ Loss of Use (60.0 x S\$4.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,328.50		

INSPECTION

Date of Assignment:	05/01/2022	Ah Lim Motor Company (AMK)
Date Inspected:	06/01/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING TOP	Necessary	32.10 FL	*32.10 FL
2	2		*REAR WINDSCREEN MOULDING LH & RH	Necessary	64.20 FL	*64.20 FL
3	1		*REAR WINDSCREEN MOULDING BTM	Necessary	32.10 FL	*32.10 FL
4	1		*TAILGATE	Bent	741.50 FL	*741.50 FL
5	1		*TAILGATE VEZEL LOGO	Necessary	43.20 FL	*43.20 FL
6	1		*TAILGATE LOCK	Repair	157.20 FL	*- FL
7	1		*TAILGATE LOCK CATCH	Repair	27.70 FL	*- FL
8	1		*TAILGATE RUBBER	Serviceable	96.80 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Serviceable	153.70 FL	*- FL
10	1		*REAR BUMPER	Buckled	532.10 FL	*532.10 FL
11	1		*REAR BUMPER CORNER RH	Serviceable	195.20 FL	*- FL
12	1		*REAR BUMPER REFLECTOR RH	Serviceable	178.20 FL	*- FL
13	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	17.50 FL	*- FL
14	8		*REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
15	1		*REAR END PANEL	Repair	538.20 FL	*- FL
16	1		*REAR END PANEL GARNISH	Serviceable	92.30 FL	*- FL
17	1		*REAR KEYLESS ANTENNA	Serviceable	58.10 FL	*- FL
18	1		*REAR SMART BUZZER	Serviceable	80.10 FL	*- FL
19	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
20	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
21	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
22	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,363.20	1,733.20
- List Item Discount on L Items 20.00/20.00% (\$)	613.64	294.64
Total Parts (\$)	2,749.56	1,438.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
2	TO REMOVE AND REINSTALL /REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
5	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD REAR END PANEL ,TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
6	TO SPRAY TAILGATE REAR BUMPER CORNER RH ,RR END PANEL	New	650.00	300.00
			Gross Labour Cost (\$\$)	1,750.00
				1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >