



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 8098J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	CRACKED	1,642.20	1,642.20
1	FRONT BUMPER NOZZLE RH	MTG CRACKED	161.45	161.45
1	FRONT BUMPER NOZZLE COVER	MISSING	51.95	51.95
1	FRONT BUMPER SENSOR RH	SHORTED	371.20	215.00
1	HEAD LAMP RH	SCRATCHED	2,501.00	2,130.60
1	FRONT SIDE MIRROR RH	TO REPAIR SEE LABOUR	1,069.40	-
	LESS 10% DISCOUNT		-	-420.12
			5,797.20	3,781.08
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES FOR EXCHANGE PARTS AS ABOVE.INCLUSIVE OF THE REPAIR OF FRONT SIDE MIRROR RH.		980.00	300.00
	RE-SPRAY PAINTING FOR FRONT BUMPER,REAR DOOR RH,REAR FENDER RH & REAR BUMPER.		980.00	660.00
	LABOUR CHARGE TO RESET FAULT CODE AND REPROGRAMMING FOR THE HEADLAMP.		480.00	120.00
			2,440.00	1,080.00
<b>GRAND TOTAL</b>			<b>8,237.20</b>	<b>4,861.08</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,850.00</b>
---	--	--	-----------------

Report Ref No. CS/TPS22000132/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.