

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG22000134/KEA3Q2  
**Date:** 16/03/2022

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070117935
Claimant Vehicle No :	SMW732X	Insured Vehicle No :	SJJ1791Y
Date of Loss:	31/12/2021	Nature of Claim:	TP
		Claim No:	7629872746SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW732X	Engine No:	R18A13042190
Make & Model:	HONDA CIVIC, 1.8 L (A)	Chassis No:	JHMF16308S219452
Reg. Date:	02/09/2008 (Man. Year: 2008)	Odometer:	311485 km
Colour:	Metallic Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	458.24	366.64	91.60	19.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,095.00	1,465.00	57.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,018.24</b>	<b>1,461.64</b>	<b>1,556.60</b>	<b>51.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,018.24</b>	<b>1,150.00</b>	<b>1,868.24</b>	<b>61.90</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,557.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,550.00</b>		

### INSPECTION

Date of Assignment:	05/01/2022		
Date Inspected:	10/01/2022	Inspected At:	Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10 Singapore 575645
Estimated Period of Repair:	4.0 days		

3/16/22, 11:50 AM

Adjuster Report

**Adjuster:** KENNETH KONG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR PROTECTOR R/LH	Dented	108.30 FL	*108.30 FL
2	1		*REAR BUMPER RETAINER/LH	Serviceable	27.00 FL	*- FL
3	1		*REAR RIM /LH	Dented	350.00 FS	*280.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					485.30	388.30
- List Item Discount on L Items 20.00/20.00% (S\$)					27.06	21.66
Total Parts (S\$)					458.24	366.64

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	0.00
2	TO CHECK WATER SEEPAGE	New	60.00	0.00
3	TO CHECK WIRING FUNCTIONS	New	60.00	15.00
4	TO CHECK COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00
5	TO REMOVE TYRE ENABLE TO REPLACE RIM & FIX SAME	New	600.00	20.00
6	TO REPAIR PANEL BEAT ON LEFT AFFECTED AREA ,REALIGN ON AFFECTED BUMPER & LABOUR TO REPLACE ABOVE PARTS	New	600.00	400.00
7	TO PUTTY PRIMER & SPRAY PAINT ON LEFT REAR DOOR ,REAR FENDER ,SIDE SILL & REAR BUMPER USING 2K PAINT	New	1,000.00	600.00
Gross Labour Cost (\$\$)			<b>2,560.00</b>	<b>1,095.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >