



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2204273

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/07/2022
Reference CC6/CTI22000136/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SME 5332D
Insured Veh. SMA 6329D
Claim No. SNM22D200112/C02
Policy No. DMPCSNA00101132102
Accident Date 04/01/2022
Inspection Date 05/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22000136/Uea3q2 Date: 12/07/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 6329D	Veh. Inspected	SME 5332D
	Policy No.	DMPCNA00101132102	Coverage (\$)	0.00
	Claim No.	SNM22D200112/C02	Excess (\$)	0.00
	Assign From		Assign Date	05/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS HYBRID (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTDZS3EUX0J033628	Colour	BLUE
	Odometer	38488 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	MICHELIN	8 mm
	L/H Front Tyre	205/60 R16	MICHELIN	8 mm
	R/H Rear Tyre	205/60 R16	MICHELIN	8 mm
	L/H Rear Tyre	205/60 R16	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/01/2022	Inspection Date	05/01/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 5332D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	1,050.00	645.23
1	REAR BUMPER REFLECTOR N/S	CRACKED	88.50	88.50
1	REAR BUMPER SIDE RETAINER N/S	CRACKED	105.50	105.50
1	REAR BUMPER SPLASH SHIELD N/S	TORN	188.20	188.20
1	REAR BUMPER LOWER GARNISH	DISTORTED	681.10	541.10
1	TAILLAMP N/S	DEFORMED / TORN	845.20	651.10
1	REAR END PANEL	TO REPAIR SEE LABOUR	615.10	-
1	REAR FENDER N/S	BADLY DENTED	1,299.20	1,121.30
1	REAR FENDER GLASS N/S	NECESSARY	950.00	645.50
1	REAR FENDER INNER TRIM BOARD N/S	DEFORMED / TWISTED	788.10	688.10
1	SET REAR FENDER INNER TRIM BOARD CLIPS N/S	NECESSARY	50.00	50.00
1	REAR FENDER UNDER COVER N/S	TORN	388.10	302.50
1	REAR FENDER INNER PANEL N/S	TO REPAIR SEE LABOUR	755.20	-
1	REAR AIR VENT N/S	DAMAGED	145.50	145.50
1	REAR DOOR N/S	TO REPAIR SEE LABOUR	1,315.10	-
1	REAR RIM CAP N/S	WARPED	350.00	350.00
1	REAR SHOCK ABSORBER N/S	TWISTED	399.10	302.80
1	REAR WHEEL HUB BEARING N/S	DAMAGED	686.00	645.10
1	REAR AXLE BEAM ASSY	BENT / TWISTED	1,951.10	1,850.50
1	FUEL LIP	TO REPAIR SEE LABOUR	205.10	-
1	FUEL LIP INNER PANEL	NOT NECESSARY	266.10	-
1	ROCKER PANEL GARNISH N/S	TORN	855.10	711.80
1	ROCKER PANEL N/S	TO REPAIR SEE LABOUR	755.10	-
1	REAR FLOOR PANEL SIDE INNER PANEL N/S	TO REPAIR SEE LABOUR	295.10	-
1	FRONT DOOR OUTER MIRROR COVER N/S	MISSING	245.00	180.60

Report Ref No. CC6/CTI22000136/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-2,303.33
			15,272.50	6,910.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TYRE N/S (SN)	SERVICEABLE	250.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR FENDER GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
1	SET ROCKER PANEL GARNISH CLIPS N/S (SN)	NECESSARY	50.00	50.00
			400.00	140.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX REAR BUMPER REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY .		120.00	80.00
	TO DISMANTLE & REPLACE REAR FENDER GLASS N/S .		120.00	100.00
	TO DISMANTLE & REFIX REAR DOOR MECHANISM .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE.		380.00	250.00
	TO DISMANTLE & REFIX FUEL TANK.		100.00	60.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO SPRAY RUST PROOFING.		100.00	40.00
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	150.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL ,REAR FENDER INNER PANEL N/S,REAR DOOR N/S,FUEL LIP ,ROCKER PANEL N/S AND REAR FLOOR PANEL SIDE INNER PANEL N/S.		1,500.00	880.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,000.00
			4,620.00	2,560.00
GRAND TOTAL			20,292.50	9,610.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,600.00
---	--	--	-----------------

Report Ref No. CC6/CTI22000136/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 5332D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 5332D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 5332D

RE-INSPECTION

