

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG22000137/GTF3E2

**Date:** 12/01/2022

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993611  
**Claimant Vehicle No :** SKV5231X **Insured Vehicle No :** SMM7145Y  
Date of Loss: 03/01/2022 Nature of Claim: TP Claim No: 8154280459SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV5231X**  
Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR6297950  
Reg. Date: 22/09/2015 (Man. Year: 2015) Chassis No: ZVW305757972  
Colour: White Odometer: 100600 km  
Engine Capacity: 1798 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 05/01/2022  
Date Inspected: 05/01/2022 Inspected At: Lye Designs (HQ)  
10 Amk Autopoint #04-04, Ang Mo Kio Industrial Park 2A  
Singapore 568047  
Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$45,000.00 (EST)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE GARNISH	Distorted	0.00 F	*- F
2	1		*FRT BUMPER	Bent	0.00 F	*- F
3	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER LH	Distorted	0.00 F	*- F
5	1		*FRT BUMPER RUBBER	Cut	0.00 F	*- F
6	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
7	1		*FRT GRILLE	Cracked	0.00 F	*- F
8	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
9	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
10	1		*FRT LH FENDER	Repair	0.00 F	*- F
11	1		*FRT LH BUMPER FOG LAMP COVER	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >