

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/CTI22000140/ETY3  
**Date:** 19/04/2022

**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00033382100
<b>Claimant Vehicle No :</b>	SNC1573A	<b>Insured Vehicle No :</b>	GBK3207U
Date of Loss:	31/12/2021	Nature of Claim:	TP

Claim No: SNM22D200023/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNC1573A</b>		
Make & Model:	BMW 218i, 1.5 (A)	Engine No:	33316428B38A15F
Reg. Date:	30/09/2021 (Man. Year: 2021)	Chassis No:	WBA12AK0507J49557
Colour:	White	Odometer:	7980 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,407.55	1,407.55	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,526.00	663.00	863.00	56.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,933.55</b>	<b>2,070.55</b>	<b>863.00</b>	<b>29.42</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>205.35</b>	<b>144.94</b>	<b>60.41</b>	<b>29.42</b>
<b>Nett Amount (S\$)</b>	<b>3,138.90</b>	<b>2,215.49</b>	<b>923.41</b>	<b>29.42</b>

**INSPECTION**

Date of Assignment:	12/04/2022	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Date Inspected:	16/02/2022	Inspected At:
Estimated Period of Repair:	2.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2022)
<b>Parts:</b>	143	BMW 218I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNC1573A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH OUTSIDE MIRROR HEATED WIT	Broken	822.50 F	*822.50 F
2	1		*LH MIRROR GLASS HEATED WIDE	Broken	416.95 F	*416.95 F
3	1		*LH OUTSIDE MIRROR COVER CAP PRIME	Broken	128.10 F	*128.10 F
4	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
F=Franchise part. S=SpcNett.						
				<b>Total Parts (S\$)</b>	<b>1,407.55</b>	<b>1,407.55</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE LEFT WING MIRROR.	New	1,275.00	425.00
2	TO RESPRAY LEFT MIRROR COVER.	New	74.00	70.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION.	New	177.00	168.00
<b>Gross Labour Cost (S\$)</b>			<b>1,526.00</b>	<b>663.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >