

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22000143/BTF3N2**Date:** 10/03/2022**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29142528AT2

Claimant Vehicle No : GBC3714P**Insured Vehicle No :** SGA881K

Date of Loss: 31/12/2021

Nature of Claim: TP

Claim No: 639575

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC3714P**

Make & Model: NISSAN NV200, 1.5 L MT ABS AIRBAG 2WD 6DR (M)

Engine No: K9KF276D126682

Reg. Date: 16/01/2012 (Man. Year: 2011)

Chassis No: VSKYBAM20U0031584

Colour: Grey

Odometer: 180383 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14C

Rear Tyre Size: 175/70R14C

Front Left Side: ROADX 6 mm

Rear Left Side: ROADX 6 mm

Front Right Side: ROADX 6 mm

Rear Right Side: ROADX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,306.42	4,546.44	3,759.98	45.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	1,740.00	4,260.00	71.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,306.42	6,286.44	8,019.98	56.06
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	14,306.42	5,000.00	9,306.42	65.05
+ GST 7.00/7.00% (S\$)	1,001.45	350.00	651.45	65.05
Nett Amount (S\$)	15,307.87	5,350.00	9,957.87	65.05

INSPECTION

Date of Assignment: 05/01/2022

Date Inspected: 06/01/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Mar 2022)	
Parts:	N/A	NISSAN NV200 1.5 L MT ABS AIRBAG 2WD 6DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC3714P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	1,056.90 FL	*1,056.90 FL
2	1		*REAR RH DOOR LOWER HINGE	Not Necessary	99.10 FL	*- FL
3	1		*REAR RH DOOR UPPER HINGE	Not Necessary	99.10 FL	*- FL
4	1		*REAR RH DOOR CHECKER	Nod Damaged	31.70 FL	*- FL
5	1		*REAR RH DOOR DCI EMBLEM	Necessary	107.80 FL	*85.00 FL
6	1		*REAR RH DOOR INNER TRIM BOARD	Nod Damaged	195.60 FL	*- FL
7	1		*REAR RH DOOR UPPER LOCK	Nod Damaged	99.80 FL	*- FL
8	1		*REAR RH DOOR LOWER LOCK	Nod Damaged	115.20 FL	*- FL
9	1		*REAR RH DOOR WEATHERSTRIP (VERTICAL)	Nod Damaged	106.00 FL	*- FL
10	1		*RH TAILLAMP	Broken	470.70 FL	*284.80 FL
11	1		*RH REAR SIDE PANEL	Dented	1,636.10 FL	*1,636.10 FL
12	1		*RH REAR SIDE PANEL AIR VENT	Broken	78.20 FL	*78.20 FL
13	1		*RH SLIDING DOOR	No such part	1,009.00 FL	*- FL
14	1		*RH SLIDING DOOR RAILING	Not Necessary	298.80 FL	*- FL
15	1		*RH SLIDING DOOR RAILING END COVER	Not Necessary	59.00 FL	*- FL
16	1		*RH REAR RIM	Nod Damaged	305.40 FL	*- FL
17	1		*RH REAR RIM CAP	Broken	168.80 FL	*71.50 FL
18	1		*RH REAR WHEEL BEARING	Jammed	794.30 FL	*395.80 FL
19	1		*REAR BUMPER	Dented	485.90 FL	*485.90 FL
20	1		*REAR BUMPER RH SIDE RETAINER	Necessary	37.20 FL	*37.20 FL
21	1		*REAR BUMPER LH SIDE RETAINER	Necessary	37.20 FL	*37.20 FL
22	1		*END PANEL	Dented	576.00 FL	*387.00 FL
23	1		*REAR BUMPER INNER SPONGE	Broken	96.00 FL	*96.00 FL
24	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
26	1		*BRAKE FLUID	Not Necessary	55.00 FS	*- FS
27	1		*REAR RH DOOR GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
28	1		*REAR RH DOOR GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
29	1		*REAR RH DOOR 6PAX STICKER	Necessary	24.00 FS	*10.00 FS
30	1		*RH REAR SIDE PANEL ADVERTISEMENT STICKER	Not Necessary	450.00 FS	*- FS
31	1		*RH REAR SIDE PANEL JOINT SEALANT	Necessary	80.00 FS	*30.00 FS
32	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,102.80	5,011.60
- List Item Discount on L Items 10.00/10.00% (S\$)	796.38	465.16
Total Parts (S\$)	8,306.42	4,546.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	1,000.00	0.00
2	SPRAY PAINTING	New	1,000.00	0.00
3	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,500.00	1,000.00
4	SPRAY PAINTING ON AFFECTED PANELS	New	1,200.00	600.00
5	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
6	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	0.00
7	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR TO ASSIST REPAIR	New	100.00	60.00
8	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH,BOARDS AND CARPET TO ASSIST REPAIR	New	380.00	0.00
9	REMOVE AND REINSTALL REAR RH DOOR GLASS TO ASSIST REPAIR	New	220.00	80.00
10	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	320.00	0.00
11	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
Gross Labour Cost (\$)			6,000.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >