



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 49J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER, OUTER MIRROR, RH (DISC 25%)	MISSING	89.50	67.13
1	MIRROR ASSY, OUTER REAR VIEW, RH (DISC 10%)	DISTORTED	1,373.50	1,236.15
1	SUPPORT, FR BUMPER RH	NOT NECESSARY	76.90	-
1	FENDER SUB-ASSY, FR, RH	NOT NECESSARY	933.10	-
1	WHEEL, DISC FRONT	NOT NECESSARY	1,555.10	-
2	HUB & BEARING ASSY, RH & LH	NOT NECESSARY	554.20	-
1	TYRE	NOT NECESSARY	126.74	-
1	COVER, FR BUMPER	TO REPAIR SEE LABOUR	495.50	-
			5,204.54	1,303.28
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF COVER, FR BUMPER.		507.00	200.00
	SPRAY PAINT.		1,116.00	480.00
	TOWING CHARGE.		56.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	NOT NECESSARY	120.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,059.00	680.00
GRAND TOTAL			7,263.54	1,983.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,600.00

Report Ref No. NS/INC22000152/Gvce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.