

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000153/UVY3E2

Date: 04/03/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00072042105
Claimant Vehicle No: SLX2170K Insured Vehicle No: EV1223S
Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: SNM22D200005/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX2170K
Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT (A) Engine No: HRA2591244A
Reg. Date: 29/03/2018 (Man. Year: 2018) Chassis No: SJNFEAJ11U228233
Colour: White Odometer: 58005 km
Engine Capacity: 1197 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,203.28	11,460.02	7,743.26	40.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,788.00	3,443.00	2,345.00	40.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	24,991.28	14,903.02	10,088.26	40.37
+ GST 7.00/7.00% (\$\$)	1,749.39	1,043.21	706.18	40.37
Nett Amount (\$\$)	26,740.67	15,946.23	10,794.44	40.37

INSPECTION

Date of Assignment: 04/01/2022
Date Inspected: 05/01/2022 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2022)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX2170K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*WHEEL ALUMINIUM	N/S Cut / O/S Repair	2,463.80 FS	*1,231.90 FS
2	1	*HARNESS ENGINE ROOM	Not Necessary	3,597.80 FN	*- FN
3	1	*FRT LH DOOR OUTER LOWER MOULDING	Not Necessary	342.60 FN	*- FN
4	1	*FRT RH DOOR OUTER LOWER MOULDING	Not Necessary	342.60 FN	*- FN
5	1	*FRT LH FENDER WHEEL ARC MOULDING	Distorted	540.50 FN	*540.50 FN
6	1	*FRT RH FENDER WHEEL ARC MOULDING	Distorted	540.50 FN	*540.50 FN
7	1	*LH FOGLAMP	Not Necessary	258.00 FS	*- FS
8	1	*RH FOGLAMP	Cracked	258.00 FS	*258.00 FS
9	1	*LH HEADLAMP (LED)	Cracked	3,243.00 FN	*3,243.00 FN
10	1	*RH HEADLAMP (LED)	Cracked	3,243.00 FN	*3,243.00 FN
11	1	*BONNET LIFT LOCK	Serviceable	89.70 FN	*- FN
12	1	*BONNET LOCK	Serviceable	50.00 FN	*- FN
13	1	*RUB-SEAL BONNET FRT	Not Necessary	64.30 FN	*- FN
14	1	*LH BONNET HINGE	Bent	59.80 FN	*59.80 FN
15	1	*RH BONNET HINGE	Bent	59.80 FN	*59.80 FN
16	1	*INSULATOR BONNET	Not Necessary	194.80 FN	*- FN
17	1	*BONNET	Dented	1,061.30 FN	*1,061.30 FN
18	1	*COVER-HOLE FRT LH FENDER TOP	Not Necessary	42.30 FN	*- FN
19	1	*COVER-HOLE FRT RH FENDER TOP	Not Necessary	65.30 FN	*- FN
20	1	*CLIP FRT WHEELHOUSE PROTECTOR	Necessary	37.80 FN	*37.80 FN
21	1	*FRT LH DEFLECTOR UNDER	Distorted	68.30 FN	*68.30 FN
22	1	*FRT RH DEFLECTOR UNDER	Distorted	68.30 FN	*68.30 FN
23	1	*FRT LH FENDER WHEELHOUSE PROTECTOR	Torn	128.30 FN	*128.30 FN
24	1	*FRT RH FENDER WHEELHOUSE PROTECTOR	Torn	128.30 FN	*128.30 FN
25	1	*FRT LH FENDER	Repair	685.00 FN	*- FN
26	1	*FRT RH FENDER	Buckled	685.00 FN	*685.00 FN
27	1	*LH AIRGUIDE	Not Necessary	90.20 FN	*- FN
28	1	*RH AIRGUIDE	Not Necessary	90.20 FN	*- FN
29	1	*EMBLEM RAD GRILLE NISSAN LOGO	Scratched	118.60 FN	*118.60 FN
30	1	*GRILLE-RADIATOR	Cracked	486.00 FN	*486.00 FN
31	1	*LH STAY FRT BUMPER	Not Necessary	134.00 FN	*- FN
32	1	*RH STAY FRT BUMPER	Not Necessary	193.70 FN	*- FN
33	1	*UPPER REINFORCEMENT FRT BUMPER	Not Necessary	755.90 FN	*- FN
34	1	*UPPER ENERGY ABSORBER FRT BUMPER	Torn	219.00 FN	*219.00 FN
35	1	*LOWER REINFORCEMENT FRT BUMPER	Not Necessary	377.90 FN	*- FN
36	1	*LOWER ENERGY ABSORBER FRT BUMPER	Not Necessary	109.50 FN	*- FN
37	1	*LH FOGLAMP BRACKET	Not Necessary	138.60 FS	*- FS
38	1	*RH FOGLAMP BRACKET	Cracked	138.60 FS	*138.60 FS
39	1	*LH FOGLAMP GARNISH	Not Necessary	110.50 FN	*- FN
40	1	*RH FOGLAMP GARNISH	Twisted	110.50 FN	*110.50 FN
41	1	*UPPER MOULDING FRT BUMPER (SHINY BLACK COLOR)	Cracked	194.20 FN	*194.20 FN
42	1	*LH SIDE BRACKET FRT BUMPER	Bent	23.40 FN	*23.40 FN
43	1	*RH SIDE BRACKET FRT BUMPER	Bent	23.40 FN	*23.40 FN
44	10	*CLIP FRT BUMPER	Necessary	13.00 FN	*13.00 FN
45	1	*FRT BUMPER	Distorted	682.90 FN	*682.90 FN
46	1	*SUNDRIES	Necessary	50.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER SENSOR	Shorted	250.00 FS	*250.00 FS
48	1		*WASHER TANK CAP COVER	Missing	2.30 FS	*2.30 FS
49	1		*WASHER TANK	Deformed	171.30 FS	*171.30 FS
50	1		*RH FOGLAMP BRACKET	Repeated	138.60 FS	*- FS
51	1		*SEAL-BONNET FRT RUBBER	Not Necessary	96.40 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

	Sub Total (\$\$)	23,036.80	13,807.00
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	3,833.52	2,346.98	
	Total Parts (\$\$)	19,203.28	11,460.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REPAIR RH SIDE RADIATOR SUPPORT, FRT RH DOOR, RENEW BONNET , BOTH FRT FENDER & FRONT	New	1,680.00	1,370.00
2	RENEW BOTH HEADLAMP AND FOCUS AND CHECK WIRING SYSTEM	New	48.00	48.00
3	APPLY SEALANT TO BONNET	New	100.00	100.00
4	PULL AND STRAIGHTENED FRONT CHASSIS	New	500.00	390.00
5	REPAIR BOTH FRT CHASSIS	New	560.00	0.00
6	PERFORM WHEEL ALIGNMENT	New	95.00	95.00
7	RENEW BOTH FRT WHEEL RIM AND BALANCING. CHECK AND INSPECT TYRE REPLACE IF NEED TO CHANGE	New	15.00	15.00
8	CHECK AND INSPECT RADIATOR REPLACE IF NEED TO CHANGE	New	120.00	0.00
9	CHECK AND INSPECT CONDENSER REPLACE IF NEED TO CHANGE	New	120.00	0.00
10	CHECK AND INSPECT A/TRANSMISSION OIL COOLER REPLACE IF NEED TO CHANGE	New	180.00	0.00
11	CHECK AND INSPECT TURBO INTER COOLER REPLACE IF NEED TO CHANGE	New	150.00	0.00
12	PRESSURE TEST RADIATOR	New	55.00	0.00
13	CHECK AND INSPECT ENGINE WIRING HARNESS REPLACE IF NEED TO CHANGE	New	240.00	0.00
14	COMPUTER CHECK DIAGNOSIS	New	120.00	120.00
15	RENEW FRONT BUMPER SENSOR	New	55.00	55.00
16	CHARGES TO SPRAY PAINTING RADIATOR SUPPORT, FRT RH DOOR, BOTH FRT FENDER, BONNET AND FRT BUMPER AND BOTH BONNET HINGE	New	1,750.00	1,250.00
Gross Labour Cost (\$\$)			5,788.00	3,443.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >