

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22000155/R1VY3E2

Date: 09/03/2022

REFERENCE

Insured/Claimant:	YONG CHOR CHIM	Policy No:	MP316928		
Date of Loss:	02/01/2022	Nature of Claim:	OD	Claim No:	MPC03069

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ1418T	Engine No:	2NRX258512
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR2B23F3901109906
Reg. Date:	24/04/2018 (Man. Year: 2018)	Odometer:	55901 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$63,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,244.00	2,280.20	5,963.80	72.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,864.40	7,212.40	3,652.00	33.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,108.40	9,492.60	9,615.80	50.32
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	18,408.40	8,792.60	9,615.80	52.24
+ GST 7.00/7.00% (S\$)	1,288.59	615.48	673.11	52.24
Nett Amount (S\$)	19,696.99	9,408.08	10,288.91	52.24

INSPECTION

Date of Assignment:	04/01/2022		
Date Inspected:	07/01/2022	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Mar 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ1418T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	200.00 FS	*100.00 FS
3	1		*BACK SENSOR 040 SUPER WHITE	Not Necessary	197.80 FS	*- FS
4	1		*COVER, RR BUMPER L/C	Deformed	557.70 FS	*557.70 FS
5	10		*PIECE, RR BUMPER	Necessary	43.00 FS	*43.00 FS
6	2		*PAD, RR BUMPER, RH	Necessary	23.40 FS	*23.40 FS
7	2		*TAPE, MOULDING, NO.1	Necessary	107.00 FS	*107.00 FS
8	1		*RETAINER, RR BUMPER	Not Necessary	164.30 FS	*- FS
9	1		*RETAINER, RR BUMPER	Not Necessary	164.30 FS	*- FS
10	1		*REINFORCEMENT SUB-AS	Not Necessary	353.10 FS	*- FS
11	1		*REFLECTOR ASSY, REFL	Not Necessary	99.80 FS	*- FS
12	1		*REFLECTOR ASSY, REFL	Not Necessary	99.80 FS	*- FS
13	1		*PANEL SUB-ASSY, BODY	Repair	786.30 FS	*- FS
14	1		*PANEL SUB-ASSY, QUAR	Repair	963.70 FS	*- FS
15	1		*TROUGH SUB-ASSY, LUG	Not Necessary	128.20 FS	*- FS
16	1		*PANEL BONDING AD	Not Necessary	267.20 FS	*- FS
17	1		*PANEL SUB-ASSY, LUGG	Bent	838.90 FS	*838.90 FS
18	1		*WEATHERSTRIP, LUGGAG	Not Necessary	186.50 FS	*- FS
19	2		*ARM SUB-ASSY, LUG CO	Not Necessary	139.40 FS	*- FS
20	1		*LOCK ASSY, LUGGAGE C	Not Necessary	423.90 FS	*- FS
21	1		*PLATE, RR FLOOR FINI	Not Necessary	295.40 FS	*- FS
22	2		*CLIP	Necessary	5.20 FS	*5.20 FS
23	1		*LUGGAGE COMP EMBLEM	Necessary	65.30 FS	*65.30 FS
24	1		*PLATE, LUGGAGE COMPT	Necessary	48.30 FS	*48.30 FS
25	1		*PLATE, LUGGAGE COMPT	Necessary	37.60 FS	*37.60 FS
26	1		*LAMP ASSY, RR COMBIN	Cracked	403.80 FS	*403.80 FS
27	1		*LAMP ASSY, RR COMBIN	Not Necessary	403.80 FS	*- FS
28	1		*RETAINER, RR BUMPER	Not Necessary	63.40 FS	*- FS
29	1		*RETAINER, RR BUMPER	Not Necessary	63.40 FS	*- FS
30	1		*LAMP ASSY, RR, LH	Not Necessary	260.60 FS	*- FS
31	1		*LAMP ASSY, RR, RH	Not Necessary	260.60 FS	*- FS
32	1		*ANTENNA, ELECTRICAL	Not Necessary	76.30 FS	*- FS
33	2		*SIKA 182010 SIKA TACK GO! (BLA	Not Necessary	216.00 FS	*- FS
34	1		*SIKA 207. G+P ADHESIVE PRIMER	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **8,244.00** **2,280.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
2	CHECK WIRING AND CONDUCT WATER TEST	New	122.40	122.40
3	REMOVE INTERIOR UPHOLSTERY TO FAC REPAUR	New	720.00	360.00
4	R/I REAR WINDSCREEN GLASS TO FAC REPAIR	New	462.00	0.00
5	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
6	SUPPLY REGN PLATE (PO#)	New	80.00	0.00
7	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN ACC AFFECTED AREAS	New	5,040.00	2,880.00
8	RESPRAY ACC AFFECTED AREAS	New	3,540.00	2,950.00
9	REMOVE AND TRANSFER BOOTLID COMPONENTS ONTO NEW BOOTLID. R/I REAR REVERSE CAMERA TO FAC REPAIR	New	540.00	540.00
Gross Labour Cost (\$\$)			10,864.40	7,212.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >