

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunus Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS22000159/GQF3N2**Date:** 23/04/2022**REFERENCE**

Insured/Claimant: SEE JIMMY Policy No: MPC21P00223800  
Date of Loss: 01/01/2022 Nature of Claim: OD Claim No: DMPC2200003H/CT

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLT8367S**  
Make & Model: MERCEDES-BENZ C200, 1.8 SPORTS (A) Engine No: 27492031163641  
Reg. Date: 14/11/2017 (Man. Year: 2017) Chassis No: WDD2050422R338855  
Colour: Grey Odometer: 70153 km  
Engine Capacity: 1991 cc  
Market Value/New Car Price: S\$132,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45 ZR18 Rear Tyre Size: 225/45 ZR18  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,170.00	8,327.00	843.00	9.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	600.00	550.00	47.83
Paintwork Labour	880.00	700.00	180.00	20.45
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,200.00</b>	<b>9,627.00</b>	<b>1,573.00</b>	<b>14.04</b>
<b>- Excess (S\$)</b>	750.00	0.00	750.00	100.00
<b>(S\$)</b>	10,450.00	9,627.00	823.00	7.88
<b>+ GST 7.00/7.00% (S\$)</b>	731.50	673.89	57.61	7.88
<b>Nett Amount (S\$)</b>	<b>11,181.50</b>	<b>10,300.89</b>	<b>880.61</b>	<b>7.88</b>

**INSPECTION**

Date of Assignment: 05/01/2022 Present Location: Vin's Motor Pte Ltd (Sin Ming)  
Date Inspected: 06/01/2022 Inspected At: Vin's Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive, #03-03, Sin Ming AutoCity  
Singapore 575722  
Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2022)
<b>Parts:</b>	M1-COUPE	MERCEDES-BENZ C200 1.8 SPORTS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLT8367S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Front RH headlamp</b> (WCP)	Broken	1,800.00 F	*1,800.00 F
2	1		<b>*Front LH headlamp</b> (WCP)	Broken	1,800.00 F	*1,800.00 F
3	1		<b>*Front RH headlamp bracket</b> (WCP)	Not Necessary	40.00 F	*- F
4	1		<b>*Front LH headlamp bracket</b> (WCP)	Not Necessary	40.00 F	*- F
5	1		<b>*Front grille base</b> (WCP)	Broken	80.00 F	*80.00 F
6	1		<b>*Front grille</b> (WCP)	Broken	120.00 F	*120.00 F
7	1		<b>*Front grille emblem</b> (WCP)	Missing	80.00 F	*80.00 F
8	1		<b>*Front grille emblem housing</b> (WCP)	Missing	50.00 F	*50.00 F
9	1		<b>*Front grille RH chrome - Top</b> (WCP)	Cut	40.00 F	*40.00 F
10	1		<b>*Front grille RH chrome - Lower</b> (WCP)	Cut	50.00 F	*50.00 F
11	1		<b>*Front grille LH chrome - Top</b> (WCP)	Cut	40.00 F	*40.00 F
12	1		<b>*Front grille LH chrome - Lower</b> (WCP)	Cut	50.00 F	*50.00 F
13	1		<b>*Front bumper</b> (WCP)	Deformed	880.00 F	*880.00 F
14	1		<b>*Front bumper centre lower bumper</b> (WCP)	Not Necessary	70.00 F	*- F
15	1		<b>*Front bumper RH fog lamp cover</b> (WCP)	Not Necessary	40.00 F	*- F
16	1		<b>*Front bumper LH fog lamp cover</b> (WCP)	Not Necessary	40.00 F	*- F
17	2		<b>*Front bumper parking sensor - Outer @ \$100.00</b> (WCP)	Damaged	200.00 F	*100.00 F
18	4		<b>*Front bumper parking sensor - Inner @ \$100.00</b> (WCP)	Damaged	400.00 F	*100.00 F
19	1		<b>*Front bumper RH side retainer</b> (WCP)	Not Necessary	50.00 F	*- F
20	1		<b>*Front bumper LH side retainer</b> (WCP)	Not Necessary	50.00 F	*- F
21	1		<b>*Front bumper air duct</b> (WCP)	Cracked	70.00 F	*70.00 F
22	1		<b>*Front bumper sponge</b> (WCP)	Cracked	110.00 F	*110.00 F
23	1		<b>*Front bumper reinforcement</b> (WCP)	Bent	250.00 F	*250.00 F
24	1		<b>*Front bumper inner top beam</b> (WCP)	Bent	140.00 F	*140.00 F
25	1		<b>*Front bumper top centre cover</b> (WCP)	Broken	50.00 F	*50.00 F
26	1		<b>*Front support panel</b> (WCP)	Bent	410.00 F	*410.00 F
27	1		<b>*Front no. plate</b>	Not Necessary	40.00 FS	*- FS

### Supplementary #1

Report was unsubmitted during this print-out.

4/23/22, 12:21 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT BONNET (WCP)	Bent	1,300.00 F	*1,300.00 F
29	1		*FRONT BONNET EMBLEM (WCP)	Necessary	50.00 F	*50.00 F
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					8,340.00	7,570.00
+ Margin on L,N Items 10.00/10.00% (S\$)					830.00	757.00
Total Parts (S\$)					9,170.00	8,327.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	880.00	700.00
<u>Labour Items</u>				
2	To refill aircon gas	New	120.00	0.00
3	To reset ECU	New	250.00	0.00
4	To repair damages	New	780.00	600.00
Gross Labour Cost (\$)			2,030.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >