

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22000163/T1qy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	12/01/2022		
	ATTN: HO WINNIE			Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	PC 2410G	Veh. Inspected	l	GX 2326M	
	Policy No.	GA461475	Coverage (\$)		0.00	
	Claim No.	S2M03PY3	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		05/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE	c.c		2986	
	Engine No.	HIDDEN	Year of Reg.		2004	
	Chassis No.	LH1621010808	Colour		SILVER	
	Odometer	589873 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185 R14	BRIDGESTONE		6 mm	
	L/H Front Tyre	185 R14	BRIDGESTONE		6 mm	
	R/H Rear Tyre	185 R14	BRIDGESTONE		6 mm	
	L/H Rear Tyre	185 R14	BRIDGESTONE		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	5. General Information					
	Accident Date	31/12/2021	Inspect Date /	Time	05/01/2022 (05:45 PM)	
	Survey held at	5 Soon Lee Street #06-03 Pionee	er Point			
	Repairer	KOO AH WHAR				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. ITHE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$12,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days					

Report Ref No. CS3/ASM22000163/T1qy3e2

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A K.K.LAU CPT(RET)

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor