



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 8738H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SIDE PANEL RH	TO REPAIR SEE LABOUR	2,979.00	-
1	REAR SIDE PANEL GLASS LH	NOT NECESSARY	1,210.10	-
1	SIDE PANEL GLASS MOULDING (FRONT) RH	NOT NECESSARY	218.00	-
1	SIDE PANEL GLASS MOULDING (CENTER) RH	NOT NECESSARY	101.00	-
1	SIDE PANEL GLASS MOULDING (REAR) RH	NOT NECESSARY	218.00	-
2	REAR BUMPER SIDE RETAINER @\$55.00	NOT NECESSARY	110.00	-
	LESS 25% DISCOUNT		-1,209.03	-
			3,627.07	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR SIDE PANEL STICKER "PRIVATE BUS" (SN)	NECESSARY	120.00	50.00
1	REAR SIDE PANEL STICKER "SPECIAL TYPE" (SN)	NECESSARY	380.00	200.00
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
1	SIDE PANEL GLASS SEALANT (FRONT) RH (SN)	NOT NECESSARY	80.00	-
1	SIDE PANEL GLASS INNER SEAL (FRONT) RH (SN)	NOT NECESSARY	60.00	-
1	SIDE PANEL GLASS SEALANT (CENTER) RH (SN)	NOT NECESSARY	80.00	-
1	SIDE PANEL GLASS INNER SEAL (CENTER) RH (SN)	NOT NECESSARY	60.00	-
1	SIDE PANEL GLASS SEALANT (REAR) RH (SN)	NOT NECESSARY	80.00	-
1	SIDE PANEL GLASS INNER SEAL (REAR) RH (SN)	NOT NECESSARY	60.00	-
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	40.00	-
1	SET SIDE PANEL INNER TRIM CLIP (SN)	NOT NECESSARY	80.00	-
			1,090.00	250.00
<u>LABOUR</u>				
	PANEL BEATING AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF SIDE PANEL RH.		1,800.00	300.00
	SPRAY PAINTING TO AFFECTED AREA.		1,800.00	400.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.	NOT NECESSARY	650.00	-
	REMOVE AND REFIX REAR SIDE PANEL GLASS RHX3.	NOT NECESSARY	480.00	-
	REMOVE AND REFIX REAR REVERSE SENSOR.	NOT NECESSARY	80.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,990.00	700.00
GRAND TOTAL			9,707.07	950.00
RECOMMENDED COST OF REPAIRS				950.00

Report Ref No. CS/SMO22000164/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.