

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000169/DQY3M4**Date:** 19/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00041322101

Claimant Vehicle No : SLG3205C **Insured Vehicle No :** GBJ4797G

Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: SNM22D200066/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG3205C**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6AT (A) Engine No: P520368095

Reg. Date: 27/09/2016 (Man. Year: 2016) Chassis No: JM6BM42A8G0342582

Colour: Grey Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,384.32	2,959.84	8,424.48	74.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,130.00	1,540.00	4,590.00	74.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,514.32	4,499.84	13,014.48	74.31
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	17,514.32	3,600.00	13,914.32	79.45
+ GST 7.00/7.00% (\$\$)	1,226.00	252.00	974.00	79.45
Nett Amount (\$\$)	18,740.32	3,852.00	14,888.32	79.45

INSPECTION

Date of Assignment: 05/01/2022

Date Inspected: 05/01/2022 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jul 2022)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6AT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG3205C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,804.00 FL	*1,026.00 FL
2	1		*BOOTLID MAZDA LOGO	Necessary	97.00 FL	*66.40 FL
3	1		*BOOTLID MAZDA 3 EMBLEM	Necessary	78.00 FL	*31.40 FL
4	1		*BOOTLID SKYACTIV EMBLEM	Necessary	86.00 FL	*32.40 FL
5	1		*BOOTLID LAMP LH	Cracked	499.00 FL	*385.00 FL
6	1		*TAIL LAMP LH	Cracked / Broken	1,690.00 FL	*790.60 FL
7	1		*TAIL LAMP PANEL LH	Not Necessary	495.00 FL	*- FL
8	1		*TAIL LAMP LOWER BRACKET LH	Not Necessary	175.00 FL	*- FL
9	1		*REAR BUMPER	Dented	1,427.00 FL	*1,061.30 FL
10	2		*REAR BUMPER SIDE RETAINER LH / RH	Serviceable	152.00 FL	*- FL
11	1		*REAR BUMPER REFLECTOR LH	Mounting Cracked	186.00 FL	*48.50 FL
12	1		*REAR BUMPER SENSOR (2PCS)	N/s Cracked/ O/s Not Necessary	506.00 FL	*183.20 FL
13	2		*REAR BUMPER SENSOR HOLDER	Serviceable	54.00 FL	*- FL
14	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	374.00 FL	*- FL
15	1		*REAR REINFORCEMENT BAR	Not Necessary	763.00 FL	*- FL
16	1		*REAR END PANEL	Repair	1,330.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	299.70 FL	*- FL
18	1		*REAR FENDER LH	Repair	2,032.00 FL	*- FL
19	1		*REAR FENDER INNER SHIELD LH	Not Necessary	336.00 FL	*- FL
20	1		*REAR FENDER AIR DUCT LH	Not Necessary	191.70 FL	*- FL
21	1		*REAR FENDER INNER TRIM LH	Not Necessary	846.00 FL	*- FL
22	1		*REAR WINDSCREEN MOULDING	Not Necessary	284.00 FL	*- FL
23	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
25	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
28	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,125.40	3,684.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,741.08	724.96
Total Parts (\$\$)	11,384.32	2,959.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	160.00	40.00
5	TO RNR REVERSE CAMERA	New	200.00	0.00
6	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	New	400.00	0.00
7	TO RNR BOOTLID MECHANISM TO ASSIST WORK LOAD	New	200.00	0.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
9	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZED DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
11	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (S\$)			6,130.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >