

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000170/KQY3N2**Date:** 07/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00082652101	
Claimant Vehicle No :	SBT3335K	Insured Vehicle No :	YM6778K	
Date of Loss:	23/12/2021	Nature of Claim:	TP	Claim No: SNM21D207514/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBT3335K		Engine No:	4B11AQ3408
Make & Model:	MITSUBISHI LANCER, 1.3 (A)		Chassis No:	JMYSTCY4A8U001400
Reg. Date:	06/06/2008 (Man. Year: 2007)		Odometer:	351363 km
Colour:	Metallic Red			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 4 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,911.00	1,766.00	145.00	7.59
Miscellaneous Items	335.00	255.00	80.00	23.88
Labour	726.60	579.60	147.00	20.23
Paintwork Labour	582.34	582.34	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,554.94	3,182.94	372.00	10.46
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	3,554.94	2,500.00	1,054.94	29.68
+ GST 7.00/7.00% (S\$)	248.85	175.00	73.85	29.68
Nett Amount (S\$)	3,803.79	2,675.00	1,128.79	29.68

INSPECTION

Date of Assignment:	05/01/2022	
Date Inspected:	05/01/2022	Inspected At: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2022)
Parts:	143	MITSUBISHI LANCER 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBT3335K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		1,911.00 F	*1,766.00 F
			Total Parts (S\$)		1,911.00	1,766.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	misc	335.00	255.00
Sub Total (\$\$)			335.00	255.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	582.34	582.34
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	726.60	579.60
Gross Labour Cost (\$\$)			1,308.94	1,161.94

Report was unsubmitted during this print-out.

< END OF ESTIMATES >