

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000171/DQY3Q2**Date:** 04/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00257572100

Claimant Vehicle No : SJE1317K **Insured Vehicle No :** SJP743L

Date of Loss: 04/01/2022 Nature of Claim: TP Claim No: SNM22D200100/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE1317K**

Make & Model: HONDA CIVIC, 1.5 (A) Engine No: R16A13003640

Reg. Date: 16/04/2008 (Man. Year: 2008) Chassis No: JHMFD46208S201220

Colour: White Odometer: 172927 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,434.74	6,663.24	14,771.50	68.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,220.00	2,140.00	4,080.00	65.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,654.74	8,803.24	18,851.50	68.17
Approved Total (Overridden) (\$\$)		7,000.00		
Nett Amount (\$\$)	27,654.74	7,000.00	20,654.74	74.69

INSPECTION

Date of Assignment: 06/01/2022

Date Inspected: 05/01/2022 Inspected At: C.s.ong Auto Pte Ltd (HQ)
10, ANG MO KIO IND PARK 2A #02-16 AMK
AUTO POINT SINGAPORE 568047
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2022)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE1317K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Buckled	937.50 FL	*537.50 FL
2	1		*FRONT FENDER INNER SHIELD RH	Deformed / Torn	194.80 FL	*103.10 FL
3	1		*FRONT FENDER QUARTER GLASS MOULDING RH	Serviceable	96.70 FL	*- FL
4	1		*FRONT WHEEL HOUSING RH	Not Necessary	1,140.00 FL	*- FL
5	1		*HEAD LAMP RH	Mtg Broken	1,412.10 FL	*1,169.40 FL
6	1		*HEAD LAMP BRACKET RH	Serviceable	99.10 FL	*- FL
7	1		*FRONT BUMPER	Cracked	938.00 FL	*692.40 FL
8	2		*FRONT BUMPER SIDE RETAINER RH/LH	Serviceable	124.40 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	242.80 FL	*- FL
10	1		*FRONT WHEEL BEARING RH	Damaged	342.60 FL	*198.20 FL
11	1		*FRONT WHEEL BEARING HUB RH	No such part	379.60 FL	*- FL
12	1		*FRONT ABSORBER RH	Distorted	507.44 FS	*450.00 FS
13	1		*FRONT LOWER ARM RH	Distorted	605.10 FL	*335.80 FL
14	1		*FRONT KNUCKLE ARM RH	Distorted	943.10 FL	*368.10 FL
15	1		*FRONT STABILIZER LINK RH	Not Necessary	296.90 FL	*- FL
16	1		*FRONT STABILIZER BAR	Not Necessary	389.40 FL	*- FL
17	1		*FRONT TIE ROD RH	Not Necessary	298.70 FL	*- FL
18	1		*FRONT TIE ROD END RH	Distorted	387.10 FL	*77.90 FL
19	1		*STEERING RACK & PINION ASSY	Broken	2,980.00 FL	*1,403.30 FL
20	1		*DRIVE SHAFT RH	Not Necessary	2,481.00 FL	*- FL
21	1		*FRONT DOOR RH	Dented	1,241.30 FL	*897.30 FL
22	1		*FRONT DOOR WEATHER STRIP RH	Necessary	296.20 FL	*225.00 FL
23	1		*FRONT DOOR CENTER MOULDING RH	Cut	296.20 FL	*107.40 FL
24	1		*FRONT DOOR WINDOW MOULDING RH	Serviceable	199.92 FL	*- FL
25	1		*FRONT DOOR HINGE RH	1 PCS Bent /1PCS Not Necessary	191.80 FL	*89.30 FL
26	1		*FRONT DOOR BLACK PLASTIC MOULDING RH	Necessary	117.52 FS	*80.00 FS
27	1		*SIDE MIRROR ASSY RH	Not Necessary	1,302.40 FL	*- FL
28	1		*SIDE SKIRT RH	Cut	789.90 FL	*693.10 FL
29	1		*ROCKER PANEL RH	Not Necessary	943.10 FL	*- FL
30	1		*FRONT FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*FRONT FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
32	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*15.00 FS
33	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*FRONT WHEEL HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*SIDE SKIRT CLIPS	Necessary	50.00 FS	*20.00 FS
36	1		*TYRE	Not Necessary	300.00 FS	*- FS
37	1		*SPORT RIM	Cut	1,500.00 FS	*500.00 FS
38	1		*FRONT BUMPER LOWER LID	Not Necessary	2,000.00 FS	*- FS
39	1		*FRONT FENDER SOUND PROOF	No	1,000.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 25,344.68 8,042.80

- List Item Discount on L Items 20.00/20.00% (\$\$) 3,909.94 1,379.56

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						21,434.74 6,663.24
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	1,000.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	800.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR FRONT FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	300.00	-
6	TO RNR FRONT UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS	New	400.00	150.00
7	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
8	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
9	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,220.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >