

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22000175/GGA3Q2**Date:** 20/06/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900015442
Claimant Vehicle No :	SHB5558U	Insured Vehicle No :	SLA4957R
Date of Loss:	01/01/2022	Nature of Claim:	TP
		Claim No:	0710656897SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5558U		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS110018
Reg. Date:	30/11/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU203575701
Colour:	Maroon	Odometer:	222326 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,276.20	1,489.11	2,787.09	65.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,293.00	770.00	1,523.00	66.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,569.20	2,259.11	4,310.09	65.61
Approved Total (Overridden) (S\$)		1,950.00		
Nett Amount (S\$)	6,569.20	1,950.00	4,619.20	70.32
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$102.72/day) (S\$)		410.88		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,567.88		
Global Sum Settlement (S\$)		2,550.00		

INSPECTION

Date of Assignment:	04/01/2022	
Date Inspected:	04/01/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	3		*PAD ,RR BUMPER ,CTR (DISC 25%)	Necessary	6.60 F	*4.95 F
2	2		*PAD ,RR BUMPER RH & LH ,3 (DISC 25%)	Necessary	7.60 F	*5.70 F
3	2		*PAD ,RR BUMPER RH & LH ,2 (DISC 25%)	Necessary	7.60 F	*5.70 F
4	2		*PAD ,RR BUMPER RH & LH ,1 (DISC 25%)	Necessary	7.60 F	*5.70 F
5	1		*COVER ,GUARD RR BUMPER LOWER (DISC 25%)	Necessary	14.80 F	*11.10 F
6	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
7	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.93 F
8	1		*LENS & BODY ASSY ,RR BUMPER RH (DISC 25%)	Cracked	486.80 F	*438.12 F
9	1		*GUARD ,RR BUMPER LOWER (DISC 25%)	Cut	558.30 F	*418.73 F
10	1		*FILLER ,RR BUMPER ,RH (DISC 25%)	Cracked	119.90 F	*89.93 F
11	1		*SENSOR REVERSE (SN)	Broken	180.00 F	*180.00 F
12	1		*ADVERTISEMENT STICKER (NPA)	Not Necessary	0.00 F	*- F
13	1		*COVER ,REAR FLOOR UNDER ,LH	Not Necessary	234.30 F	*- F
14	1		*COVER ,REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
15	1		*COVER ,REAR FLOOR UNDER ,RH	Not Necessary	169.50 F	*- F
16	1		*COVER ,REAR COMBINATION LAMP ,RH	Not Necessary	54.00 F	*- F
17	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Not Necessary	438.10 F	*- F
18	1		*ANTENNA ELECTRICAL KEY	Not Necessary	60.30 F	*- F
19	1		*RETAINER ,RR BUMPER ,LH	Not Necessary	111.50 F	*- F
20	1		*SEAL ,RR BUMPER ,LH	Not Necessary	85.20 F	*- F
21	1		*SEAL ,RR BUMPER ,RH	Not Necessary	85.20 F	*- F
22	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
23	1		*END PANEL COVER ,DECK TRIM SERVICE HOLE	Not Necessary	47.00 F	*- F
24	1		*END PANEL, COVER DECK TRIM REAR	Not Necessary	122.80 F	*- F
25	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
26	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F

F=Franchise part.

Total Parts (\$\$) **4,276.20** **1,489.11**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	807.00	400.00
2	SPRAY PAINT	New	936.00	300.00
3	TO CHECK & RESET SYSTEM FUNCTION	New	150.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	40.00	0.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	40.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$)			2,293.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >