

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22000176/KGA3Q2**Date:** 03/08/2022**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMY7896A	Insured Vehicle No :	SLM4934T
Date of Loss:	31/12/2021	Nature of Claim:	TP
		Claim No:	MFL2022D0000083

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY7896A	Engine No:	1NZR826130
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	NHP1707189150
Reg. Date:	25/03/2021 (Man. Year: 2019)	Odometer:	45424 km
Colour:	Metallic Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,575.00	4,995.71	7,579.29	60.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	2,300.00	1,950.00	45.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,825.00	7,295.71	9,529.29	56.64
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	16,825.00	5,800.00	11,025.00	65.53
+ GST 7.00/7.00% (S\$)	1,177.75	406.00	771.75	65.53
Nett Amount (S\$)	18,002.75	6,206.00	11,796.75	65.53
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,419.45		

INSPECTION

Date of Assignment:	05/01/2022		
Date Inspected:	06/01/2022	Inspected At:	Car Times Autolution Pte Ltd (HQ) 160 Sin Ming Drive #02-04, AutoCity Singapore 575722
Estimated Period of Repair:	10.0 days		

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2022)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY7896A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,200.00 FL	*1,200.00 FL
2	1		*REAR TAILGATE INNER TRIM	Serviceable	200.00 FL	*- FL
3	1		*REAR TAILGATE LOCK ASSY	Jammed	200.00 FL	*200.00 FL
4	1		*TAILGATE CENTRE GARNISH	Serviceable	150.00 FL	*- FL
5	1		*REAR TAIL LAMP PANEL LHS	Repair	100.00 FL	*- FL
6	1		*REAR TAIL LAMP PANEL RHS	Repair	100.00 FL	*- FL
7	1		*REAR TAIL LAMP LHS	Mtg Cracked	320.00 FL	*320.00 FL
8	1		*REAR TAIL LAMP RHS	Mtg Cracked	320.00 FL	*320.00 FL
9	1		*REAR TAILGATE LAMP LHS	Mtg Cracked	300.00 FL	*300.00 FL
10	1		*REAR TAILGATE LAMP RHS	Serviceable	300.00 FL	*- FL
11	1		*REAR BUMPER	Bent	400.00 FL	*350.20 FL
12	1		*REAR BUMPER RETAINER LHS	Serviceable	80.00 FL	*- FL
13	1		*REAR BUMPER RETAINER RHS	Serviceable	80.00 FL	*- FL
14	1		*REAR TOYOTA EMBLEM	Necessary	80.00 FL	*80.00 FL
15	1		*REAR HYBRID EMBLEM	Necessary	70.00 FL	*70.00 FL
16	1		*REAR BUMPER CENTRE TRIM	Bent	200.00 FL	*200.00 FL
17	1		*REAR BUMPER LHS TRIM	Dented / Cut	180.00 FL	*180.00 FL
18	1		*REAR BUMPER RHS TRIM	Serviceable	180.00 FL	*- FL
19	1		*REAR BUMPER REFLECTOR RHS	Serviceable	100.00 FL	*- FL
20	1		*REAR BUMPER REFLECTOR LHS	Serviceable	100.00 FL	*- FL
21	1		*REAR FENDER LHS	Repair	1,500.00 FL	*- FL
22	1		*REAR FENDER RHS	Repair	1,500.00 FL	*- FL
23	1		*REAR FENDER INNER TRIM LHS	Serviceable	400.00 FL	*- FL
24	1		*REAR FENDER INNER TRIM RHS	Serviceable	400.00 FL	*- FL
25	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
26	1		*END PANEL OUTER	Bent	710.00 FL	*689.75 FL
27	1		*END PANEL INNER	Bent	400.00 FL	*400.00 FL
28	1		*REAR FENDER INNER TRIM LHS	Serviceable	630.00 FL	*- FL
29	1		*REAR FENDER INNER TRIM RHS	Serviceable	630.00 FL	*- FL
30	1		*END PANEL TOP GARNISH	Dented	150.00 FL	*150.00 FL
31	1		*SMART BUZZER	Cracked	100.00 FL	*100.00 FL
32	1		*SPARE TYRE PANEL	Bent / Buckled	700.00 FL	*700.00 FL
33	1		*TAIL LAMP INNER PANEL BRACKET LHS	Repair	200.00 FL	*- FL
34	1		*TAIL LAMP INNER PANEL BRACKET RHS	Repair	200.00 FL	*- FL
35	1		*TAILGATE WEATHERSTRIP	Distorted / Dented	400.00 FL	*361.00 FL
36	1		*SPARE TYRE PANEL	Repair	900.00 FL	*- FL
37	1		*FLOORBOARD	Serviceable	1,200.00 FL	*- FL
38	1		*FLOORBOARD COVER	Serviceable	500.00 FL	*- FL
39	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
40	1		*REAR CARPLATE W/HOLDER	Serviceable	60.00 FS	*- FS
41	1		*REAR SENSORS	Shorted	200.00 FS	*200.00 FS
42	1		*DASH CAM	Serviceable	300.00 FS	*- FS
43	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
44	1		*CEREMIC COATING (REAR BUMPER /TAILGATE)	Necessary	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,400.00 6,430.95

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					3,825.00	1,435.24
Total Parts (S\$)					12,575.00	4,995.71
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,800.00	1,200.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,600.00	800.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	100.00	20.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	90.00
5	REMOVE & REFIT REAR UPHOLSTERY	New	300.00	80.00
6	TRANSFER TAILGATE PARTS	New	150.00	60.00
7	DIGNOSTIC CHECK	New	100.00	0.00
8	REMOVE & REFIT REAR SENSORS	New	100.00	50.00
Gross Labour Cost (\$)			4,250.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >