HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP.111

Veron.

19,041.70

4,760.43 14,281.28

ESTIMATE

Name : SEE TECK HIN Vehicle No : SKV 6119 G Make/Model: TOYOTA HARRIER

Accident date: 05.01.2022 754 60006/399

No DESCRIPTION	Qty	Amount (S\$)
List Items		
1:Rear windscreen rubber	1	\$ 144.50
2 Tailgate Distorted	1	\$ 2,616.90
3:Tailgate hinges @ \$148.50 // ~	2	\$ 297.00
4 Tailgate upper lock	1	\$ 1,071.40
5 Tailgate lower lock	1	\$ 50.60
6 Tailgate shock absorber @ \$258.50	2	\$ 517.00
7:Tailgate centre logo xhe ^~	1	\$ 66.00
8:Tailgate "Harrier" emblem Nev	1	\$ 121.00
9 Tailgate side reflector @ \$547.80 RH could	2	\$ 1,095.60
10:Tailgate handle ************************************	1	\$ 48.30
11 Tailgate inner cover Cruco	1	\$ 636.40
12:Tailgate weather strip	1	\$ 486.20
13 Tailgate inner side rubber @ \$1,107.40	2	\$ 2,214.80
14 Rear tailgate top garnish \mathcal{H}	1	\$ 1,230.00
15 Rear number plate lamp @ \$177.00 \ M	2	\$ 354.00
16:Rear lamp @ \$511.50 RH audd	2	\$ 1,023.00
17:Rear lamp lower holder @ \$104.30 He M	2	\$ 208.60
18 Rear bumper De Le	1	\$ 1,883.20
19 Rear bumper side holder @ \$188.70	2	\$ 377.40
20:Rear bumper lower garnish	1	\$ 617.50
21 Rear bumper inner sponge	1	\$ 137.50
22;Rear bumper lower reflector @ \$63.40 *** N	2	\$ 126.80
23 Rear end panel Dented	1	\$ 858.00
24 Rear end panel inner top garnish De kand	1	\$ 489.50
25 Rear spare tyre top board 2000-0	1	\$ 973.50
26 Rear side garnish @ \$698.50 RH De L	2	\$ 1,397.00

693585

Less 25% Disc

Total

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883 Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : SEE TECK HIN Vehicle No : SKV 6119 G Make/Model: TOYOTA HARRIER Accident date: 05.01.2022

0	DESCRIPTION	Qty	Amount (S\$)
Special Nett Item	<u>is</u>		
1 Rear bumper rev	erse sensor @ \$467.50	dad 2	\$ 935.00
2 Rear bumper clip		1	\$ 60.00
3 Rear camera	the hu	1	\$ 800.00
	380	Total	\$ 1,795.00
Labour Cost			<u></u>
1 To supply rear wi	ndscreen sealant		\$ 50.00
2 To supply rear en	d panel inner sealant		\$ 200.00
3 Remove & reinsta	all rear windscreen		\$ 200.00
4 Remove & reinst	all bootlid inner garnish		\$ 200.00
5 Remove & reinsta	all reverse sensor		\$ 200.00
6 Remove ,replace	& repair consistent to the acciden	t	\$ 1,800.00
7 Respray painting			\$ 1,500.00
0'= (0)			\$ _150.00
9 Remove and (li)	istall upholslery 150 istall rear carriers 11 install tailgate Spoules	70 Total	\$ 4,300.00
v Remove and rei	istall rear carriers.	Grand Total	\$ 20,376.28

2630

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 9865.85 L/s: 74 K. 06 Days.

