

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000182/ATY3N2**Date:** 12/05/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00165072100

Claimant Vehicle No : SKN52X **Insured Vehicle No :** SKC5561T

Date of Loss: 26/12/2021 Nature of Claim: TP **Claim No:** SNM22D200098/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN52X**

Make & Model: TOYOTA ISIS, 1.8 LXA (A) Engine No: 1ZZ3172720

Reg. Date: 27/11/2008 (Man. Year: 2008) Chassis No: ZNM100058423

Colour: Black Odometer: 243490 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 12,574.15 | 2,300.15 | 10,274.00 | 81.71 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,620.00 | 1,060.00 | 3,560.00 | 77.06 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 17,194.15 | 3,360.15 | 13,834.00 | 80.46 |
| Approved Total (Overridden) (S\$) | | 2,700.00 | | |
| Nett Amount (S\$) | 17,194.15 | 2,700.00 | 14,494.15 | 84.30 |

INSPECTION

Date of Assignment: 05/01/2022

Date Inspected: 06/01/2022 Inspected At: SR AUTOWORKS PTE LTD (HQ)
8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit #02-24
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 12 May 2022) |
| Parts: 144 | TOYOTA ISIS 1.8 LXA (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SKN52X) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|---------------|-------------|------------|
| 1 | 1 | | *FRONT BUMPER | Distorted | 788.00 FL | *788.00 FL |
| 2 | 1 | | *FRONT BUMPER SIDE RETAINER | N/s Damaged | 250.00 FL | *125.00 FL |
| 3 | 1 | | *FRONT BUMPER FOGLAMP COVER LH | Deformed | 79.20 FL | *79.20 FL |
| 4 | 1 | | *FRONT BUMPER UNDER GARNISH | Not Necessary | 452.00 FL | *- FL |
| 5 | 1 | | *FRONT BUMPER REINFORCEMENT | Dented | 435.00 FL | *435.00 FL |
| 6 | 1 | | *HEAD LAMP LH | Cracked | 763.00 FL | *763.00 FL |
| 7 | 1 | | *HEAD LAMP BOTTOM RETAINER LH | Bent | 122.00 FL | *122.00 FL |
| 8 | 1 | | *FRONT GRILLE | Not Necessary | 542.70 FL | *- FL |
| 9 | 1 | | *SUPPORT PANEL | Not Necessary | 987.20 FL | *- FL |
| 10 | 1 | | *BRACE PANEL | Not Necessary | 217.00 FL | *- FL |
| 11 | 1 | | *RADIATOR | Not Necessary | 1,332.00 FL | *- FL |
| 12 | 1 | | *AIR CON CONDENSER | Not Necessary | 977.50 FL | *- FL |
| 13 | 1 | | *AIR CON PIPE | Not Necessary | 334.00 FL | *- FL |
| 14 | 1 | | *AIR CON SUCTION PIPE | Not Necessary | 368.00 FL | *- FL |
| 15 | 1 | | *AIR CON DISCHARGE PIPE | Not Necessary | 354.20 FL | *- FL |
| 16 | 1 | | *FRONT FENDER LH | Dented | 1,025.00 FL | *688.00 FL |
| 17 | 1 | | *FRONT FENDER INNER COWLING LH | Not Necessary | 135.00 FL | *- FL |
| 18 | 1 | | *FRONT FENDER END GARNISH LH | Not Necessary | 85.00 FL | *- FL |
| 19 | 1 | | *FRONT SHOCK ABSORBER LH | Not Necessary | 517.80 FL | *- FL |
| 20 | 1 | | *FRONT LOWER ARM LH | Not Necessary | 520.50 FL | *- FL |
| 21 | 1 | | *FRONT KNUCKLE ARM LH | Not Necessary | 599.70 FL | *- FL |
| 22 | 1 | | *FRONT KNUCKLE BEARING LH | Not Necessary | 197.50 FL | *- FL |
| 23 | 1 | | *FRONT DRIVESHAFT LH | Not Necessary | 1,028.00 FL | *- FL |
| 24 | 1 | | *STABILIZER LINK LH | Not Necessary | 204.60 FL | *- FL |
| 25 | 1 | | *SIDE MIRROR LH | Not Necessary | 676.80 FL | *- FL |
| 26 | 1 | | *FRONT DOOR RH | Not Necessary | 1,080.50 FL | *- FL |
| 27 | 1 | | *FRONT BUMPER CLIPS | Necessary | 50.00 FS | *50.00 FS |
| 28 | 1 | | *SUPPORT PANEL SEALANT | Not Necessary | 80.00 FS | *- FS |
| 29 | 1 | | *RADIATOR COOLANT | Not Necessary | 80.00 FS | *- FS |
| 30 | 1 | | *FRONT GRILLE CLIP | Not Necessary | 40.00 FS | *- FS |
| 31 | 1 | | *FRONT FENDER SEALANT LH | Not Necessary | 80.00 FS | *- FS |
| 32 | 1 | | *FRONT FENDER INNER COWLING CLIPS | Not Necessary | 60.00 FS | *- FS |
| 33 | 1 | | *WINDSCREEN SIDE MOULDING CLIPS | Not Necessary | 50.00 FS | *- FS |
| 34 | 1 | | *FRONT TYRE LH | Not Necessary | 380.00 FS | *- FS |
| 35 | 1 | | *FRONT SPORT RIM LH | Not Necessary | 1,200.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$) | 16,092.20 | 3,050.20 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 3,518.05 | 750.05 |
| Total Parts (\$) | 12,574.15 | 2,300.15 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS | New | 1,600.00 | 500.00 |
| 2 | TO SPRAY PAINT AFFECTED AREA | New | 1,600.00 | 500.00 |
| 3 | TUFF COAT | New | 250.00 | 30.00 |
| 4 | WIRING AND BULB CHECK | New | 50.00 | 30.00 |
| 5 | REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS | New | 200.00 | 0.00 |
| 6 | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | New | 200.00 | 0.00 |
| 7 | REMOVE AND REFIX FRONT UNDERCARRIAGE | New | 600.00 | 0.00 |
| 8 | CONDUCT WHEEL ALIGNMENT | New | 120.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 4,620.00 | 1,060.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >