

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21011481/RVF3E2-1

Date: 10/02/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMW9881P Insured Vehicle No : SLK2921D
Date of Loss: 09/11/2021 Nature of Claim: TP Claim No: MFL2021D0004889

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW9881P**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 Standard (AUTO) (2WD) (A) Engine No: 1ZR0G35650
Reg. Date: 11/12/2020 (Man. Year: 2020) Chassis No: MR2BE3BEX00011911
Colour: Blue Odometer: 26286 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,423.25	3,526.68	3,896.57	52.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,260.00	1,260.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,943.25	4,786.68	5,156.57	51.86
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	9,943.25	3,800.00	6,143.25	61.78
+ GST 7.00/7.00% (S\$)	696.03	266.00	430.03	61.78
Nett Amount (S\$)	10,639.28	4,066.00	6,573.28	61.78

INSPECTION

Date of Assignment: 06/01/2022
Date Inspected: 11/11/2021 Inspected At: Toh Painting & Services Pte Ltd (HQ)
BLK 3 WOODLANDS ROAD, UNIT 391C&G YEOW TEE INDUSTRIAL ESTATE
Singapore 677966
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Feb 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 Standard (AUTO)(2WD) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMW9881P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	942.65 FL	*890.00 FL
2	1		*BOOTLID LOCK	Bent / Jammed	439.56 FL	*256.00 FL
3	1		*BOOTLID LOCK CATCH	Not Necessary	61.59 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP	Distorted	230.56 FL	*230.56 FL
5	2		*BOOTLID HINGE	Bent / Twisted	180.18 FL	*180.18 FL
6	2		*BOOTLID RUBBER STOPPER	Necessary	41.58 FL	*41.58 FL
7	1		*BOOTLID EMBLEM LOGO	Necessary	61.16 FL	*61.16 FL
8	1		*BOOTLID EMBLEM COROLLA	Necessary	44.99 FL	*44.99 FL
9	1		*BOOTLID EMBLEM ALTIS	Necessary	50.22 FL	*50.22 FL
10	2		*BOOTLID REVERSE LAMP	Not Necessary	2,687.74 FL	*- FL
11	1		*BOOTLID GARNISH	Serviceable	219.95 FL	*- FL
12	1		*TAILLAMP	N/S Cracked / Broken	1,627.56 FL	*813.78 FL
13	2		*TAILLAMP LOWER BRACKET	Not Necessary	145.10 FL	*- FL
14	1		*REAR BUMPER	Dented / Deformed	650.76 FL	*581.00 FL
15	2		*REAR BUMPER REFLECTOR	Serviceable	109.12 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Dented / Bent	372.85 FL	*287.00 FL
17	2		*REAR BUMPER RETAINER	Not Necessary	221.44 FL	*- FL
18	1		*REAR BUMPER TOW HOOK COVER	Serviceable	20.79 FL	*- FL
19	1		*REAR END PANEL	Dented / Warped	736.45 FL	*616.00 FL
20	1		*REAR END PANEL GARNISH	Deformed	307.56 FL	*278.00 FL
21	1		*REAR END PANEL GARNISH COVER	Not Necessary	67.66 FL	*- FL
22	1		*REVERSE SENSOR (2PCS)	Damaged (1Pc Only)	530.20 FL	*265.10 FL
23	1		*SET BOOTLID INNER TRIM BOARD CLIP	Necessary	34.00 FS	*30.00 FS
24	1		*SET REAR END PANEL GARNISH CLIP	Necessary	22.00 FS	*20.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	55.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,860.67	4,675.57
- List Item Discount on L Items 25.00/25.00% (S\$)	2,437.42	1,148.89
Total Parts (S\$)	7,423.25	3,526.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR & REPLACE DAMAGED PARTS	New	1,000.00	500.00
2	SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	REMOVE & REFIX TRIM BOARD & GARNISH	New	100.00	60.00
4	REMOVE & REFIX REVERSE SENSOR	New	80.00	60.00
5	CHECK REAR WIRING SYSTEM	New	40.00	0.00
6	SPRAY ANTI RUST ON AFFECTED AREA	New	100.00	40.00
			Gross Labour Cost (\$)	1,260.00
			2,520.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >