

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 9873X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	UNIT FRONT BONNET	BENT	1,380.00	1,380.00
1	UNIT FRONT GRILL	CRACKED	530.00	530.00
1	UNIT FRONT GRILL EMBLEM	MISSING	150.00	150.00
1	UNIT FRONT NUMBER PLATE BASE	CRACKED	148.00	148.00
2	UNITS FRONT BONNET SPRING @\$38.00	SERVICEABLE	76.00	-
1	UNIT FRONT BUMPER CENTRE GRILL	SERVICEABLE	168.00	-
1	UNIT FRONT BUMPER	BUCKLED	1,650.00	1,480.00
1	UNIT FRONT BUMPER L/H LOWER MOULDING	CRACKED	98.00	98.00
1	UNIT FRONT BUMPER REINFORCEMENT	BENT	480.00	480.00
1	UNIT FRONT HEAD LAMP ASSY RH	MTG CRACKED	980.00	980.00
2	UNITS FRONT BUMPER SIDE RETAINER @\$156.00	SERVICEABLE	312.00	-
1	UNIT FRONT BUMPER R/H LOWER MOULDING (ADDITIONAL)	DENTED	98.00	98.00
	LESS 10% DISCOUNT		-	-534.40
			6,070.00	4,809.60
	SPECIAL NETT ITEMS			
1	UNIT FRONT NUMBER PLATE (SN) }	BENT	48.00	45.00
1	UNIT FRONT NUMBER PLATE CASING (SN) }	BENT	28.00	-
2	UNIT ENGINE MOUNTING @\$280.00 (\$498.00)(50%)(SN) (ADDITIONAL)	CRACKED	560.00	249.00
1	UNIT AUTO TRANSMISSION MOUNTING (50%)(SN) (ADDITIONAL)	CRACKED	180.00	90.00
			816.00	384.00
	<u>LABOUR</u>			
	COMPUTER 4 WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	FOR PANEL BEATING & REPLACE ABOVE DAMAGED PARTS.		800.00	500.00
	FOR RESPRAY PAINTING DAMAGED PARTS.		900.00	500.00
	CAR TOWING.		80.00	80.00

Report Ref No. CS/SMO22000188/Ktf3n2



(TO ITS PRE-ACCIDENT CONDITION)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	WORKMANSHIP FOR REMOVE & FIXING ABOVE DAMAGED PARTS (ADDITIONAL).		150.00	80.00
			2,010.00	1,160.00
	GRAND TOTAL		8,896.00	6,353.60
	RECOMMENDED COST OF LUMP SUM REPAIRS			5,050.00

Report Ref No. CS/SMO22000188/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser