



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000189/Atf3e2 Date: 02/05/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMM 9604B	Veh. Inspected	SMP 6474M
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200001/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	06/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT	c.c	1317
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GK33423669	Colour	GREY
	Odometer	37781 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
	L/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
	R/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm
	L/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/12/2021	Inspection Date	06/01/2022
	Survey held at	SR AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR (FRONT):		6 Working Days	
	ESTIMATED NORMAL PERIOD FOR REPAIR (REAR):		10 Working Days	