

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS4/CTI22000190/NTY3E2

Date: 23/06/2022

REFERENCE

Insured/Claimant: SUHAIMI BIN ABU AMIN Policy No: DMPCNSA00179692101

Date of Loss: 23/12/2021

Nature of Claim: OD

Claim No: SNM21D207649/C01/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY8264C**

Make & Model: HONDA CIVIC, 1.8 L 5AT (A)

Engine No: R18A15000265

Reg. Date: 05/10/2010 (Man. Year: 2009)

Chassis No: JHMFD1630AS200066

Colour: Red

Odometer: 193426 km

Engine Capacity: 1799 cc

Market Value/New Car Price: S\$65,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Kumho 8 mm

Rear Left Side: Kumho 8 mm

Front Right Side: Kumho 8 mm

Rear Right Side: Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,642.00	13,164.00	15,478.00	54.04
Miscellaneous Items	130.00	130.00	0.00	0.00
Labour	1,835.40	1,835.40	0.00	0.00
Paintwork Labour	944.51	944.51	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,551.91	16,073.91	15,478.00	49.06
- Excess (S\$)	750.00	1,000.00	-250.00	-33.33
(S\$)	30,801.91	15,073.91	15,728.00	51.06
+ GST 7.00/0.00% (S\$)	2,156.13	0.00	2,156.13	100.00
Nett Amount (S\$)	32,958.04	15,073.91	17,884.13	54.26

INSPECTION

Date of Assignment: 06/01/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 07/01/2022 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)

Estimated Period of Repair: 0.0 days
6 Marsiling Lane
Singapore 739145

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$12,127.00 NETT)

TOTAL LOSS ASPECT

Market Value :	\$65,000.00
OMV :	\$25,959.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$34,935.00
COE Rebate (2) :	\$30,509.00
Total Rebate (1) + (2) = :	\$30,509.00

The total amount incurred will be Market Value \$65,000.00 minus Total Rebate \$30,509.00 = \$34,491.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2022)

Parts: 143 HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJY8264C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		28,642.00 F	*13,164.00 F
					Total Parts (S\$)	13,164.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	130.00	130.00
			Sub Total (\$\$)	130.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	944.51	944.51
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	1,835.40	1,835.40
			Gross Labour Cost (\$\$)	2,779.91

Report was unsubmitted during this print-out.

< END OF ESTIMATES >