

Your Ref : SNM21D207649/C01/TANKW

Date: 23th Jun 2022

Our Ref : CS4/CTI22000190/Nty3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJY 8264C
ACCIDENT ON 23/12/2021**

Instruction was received to inspect the vehicle Reg. No. SJY 8264C. The inspection was conducted on 07/01/2022 at the premises of M/s Auto Insure Pte Ltd, 6 Marsiling Lane, Singapore 739145.

The following vehicle information was recorded:

Registration Number	: SJY 8264C
Make/Model	: Honda Civic 1.8L 5AT
Year of Registration	: 2010
Body Colour	: Red
Chassis Number	: JHMFD1630AS200066
Engine Capacity	: 1799 cc

The vehicle caught fire. The cause of fire probably due to roadworthy engine burnt.
(Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 65,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 30,509.00
Nett Liability	<u>S\$ 34,491.00</u> =====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.