1/11/22, 3:02 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000192/UVY3N2

11/01/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00069252101

Claimant Vehicle No:

FBM8279T

No:

Insured Vehicle GBK3289H

Date of Loss:

31/12/2021

Nature of Claim: TP

Claim

Odometer:

SNM22D200015/C02/TANKL

20386 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBM8279T Reg No:

HONDA NC750XA, 745cc RC88E5101562 Make & Model: Engine No: Reg. Date: 23/04/2018 (Man. Year: 2018) Chassis No: JH2RC90AXJK201462

Colour: Blue

Engine Capacity: 745 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 120/70R17 Rear Tyre Size: 160/60R17 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: Rear Right Side: $0 \, \text{mm}$ 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,523.00	2,341.00	182.00	7.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	200.00	50.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,773.00	2,541.00	232.00	8.37
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	2,773.00	2,000.00	773.00	27.88

INSPECTION

Date of Assignment: 05/01/2022

Teo Spray Painting (HQ)

BLK 6 DEFU LANE 10, DEFU IND PARK C #01-Date Inspected: 06/01/2022 Inspected At:

558

Singapore 539187

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 Jan 2022)

Parts: N/A HONDA NC750XA 745cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBM8279T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	280.00 FL	*260.00 FL
2	1		*SIDE MIRROR RH	Cut	120.00 FL	*120.00 FL
3	1		*EXHAUST	Dented	780.00 FL	*780.00 FL
4	1		*EXHAUST PROTECTOR	Scratched	120.00 FL	*120.00 FL
5	1		*CRASH BAR	Cut	480.00 FL	*480.00 FL
6	1		*BRAKE PANNEL	Serviceable	140.00 FL	*- FL
7	1		*HAND GUARD	Cut	250.00 FL	*250.00 FL
8	1		*WIND SHIELD	Cracked	380.00 FL	*380.00 FL
9	1		*NUMBER PLATE	Necessary	48.00 FS	*10.00 FS
10	1		*TOP BOX	Cut	180.00 FS	*180.00 FS
F=Fra	ınchise	part. S=SpcNett.		Sub Total (S\$)	2,778.00	2,580.00
			- List Item Disco	unt on L Items 10.00/10.00% (S\$)	255.00	239.00
				Total Parts (S\$)	2,523.00	2,341.00
			Report was u	insubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
Labour Items			
1 LABOUR CHARGES	New	250.00	200.00
	Gross Labour Cost (S\$)	250.00	200.00
Repo	t was unsubmitted during this print-out.		

< END OF ESTIMATES >