

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22000193/ATF3N2**Date:** 25/05/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBL1162Y **Insured Vehicle No :** YQ3138G
 Date of Loss: 05/01/2022 Nature of Claim: TP Claim No: CDMCG22000031

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL1162Y**
 Make & Model: TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A) Engine No: 1GD8676666
 Reg. Date: 23/03/2021 (Man. Year: 2021) Chassis No: GDH2012016832
 Colour: White Odometer: 9563 km
 Engine Capacity: 2754 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70 R15C Rear Tyre Size: 195/70 R15C
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,839.27	17,928.75	13,910.52	43.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,040.00	4,190.00	4,850.00	53.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,879.27	22,118.75	18,760.52	45.89
Approved Total (Overridden) (S\$)		17,700.00		
Nett Amount (S\$)	40,879.27	17,700.00	23,179.27	56.70

INSPECTION

Date of Assignment: 06/01/2022
 Date Inspected: 07/01/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 May 2022)	
Parts:	N/A	TOYOTA HIACE 1.8 D SUPER GL DARK PRIME (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL1162Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	495.70 FL	*495.70 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	360.00 FL	*360.00 FL
3	1		*FRONT BUMPER CENTRE BEAM	Bent	286.40 FL	*286.40 FL
4	2		*FRONT BUMPER FOGLAMP COVER	Not Necessary	196.60 FL	*- FL
5	1		*FRONT BUMPER CENTRE BEAM	Repeated	475.20 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	398.50 FL	*398.50 FL
7	2		*HEADLAMP (LED)	Cracked	6,191.00 FL	*5,168.00 FL
8	1		*FRONT GRILLE BASE	Cracked	360.00 FL	*360.00 FL
9	1		*FRONT GRILLE (LOWER)	Cracked	198.60 FL	*198.60 FL
10	1		*FRONT GRILLE UPPER COVER GARNISH	Cracked	491.90 FL	*491.90 FL
11	1		*FRONT GRILLE CENTER COVER GARNISH	Cracked	365.40 FL	*365.40 FL
12	2		*FRONT DOOR STEP PANEL GARNISH	Not Necessary	396.20 FL	*- FL
13	1		*BONNET	Dented	1,135.40 FL	*825.00 FL
14	1		*BONNET LOGO	Necessary	80.10 FL	*80.10 FL
15	2		*BONNET SIDE RUBBER	Not Necessary	76.00 FL	*- FL
16	1		*BONNET LOCK	Not Necessary	95.00 FL	*- FL
17	1		*FRONT BRACE PANEL	Bent	89.50 FL	*89.50 FL
18	1		*RADIATOR SUPPORT PANEL	Dented	796.20 FL	*796.20 FL
19	1		*RADIATOR	Dented	2,250.00 FL	*1,817.00 FL
20	1		*RADIATOR SPARE TANK	Not Necessary	108.40 FL	*- FL
21	1		*AIR CON CONDENSER	Dented	1,447.80 FL	*1,447.80 FL
22	4		*AIR CON BRACKET	Not Necessary	512.00 FL	*- FL
23	2		*AIR CONDENSER SIDE GARNISH	Not Necessary	58.80 FL	*- FL
24	1		*AIR COOLER	Not Necessary	1,984.70 FL	*- FL
25	2		*AIR COOLER BRACKET	Not Necessary	596.20 FL	*- FL
26	2		*COOLER AIR GUARD	Not Necessary	422.20 FL	*- FL
27	2		*COOLER AIR GUARD RUBBER	Not Necessary	220.00 FL	*- FL
28	1		*WASHER TANK	Not Necessary	210.30 FL	*- FL
29	1		*ADBULB TANK	Not Necessary	983.40 FL	*- FL
30	1		*AIR CLEANER BOX	Not Necessary	794.60 FL	*- FL
31	1		*TAILGATE	Distorted	1,850.00 FL	*1,850.00 FL
32	1		*TAILGATE WINDSCREEN GLASS	Chipped	1,351.70 FL	*1,351.70 FL
33	1		*TAILGATE OUTER MOULDING	Cracked	324.00 FL	*324.00 FL
34	1		*TAILGATE OUTER HANDLE	Not Necessary	149.00 FL	*- FL
35	1		*TAILGATE RUBBER PLATE LAMP	Not Necessary	65.30 FL	*- FL
36	1		*TAILGATE LOGO	Necessary	50.00 FL	*50.00 FL
37	1		*TAILGATE HIACESTICKER	Necessary	59.00 FL	*59.00 FL
38	2		*TAILGATE CORNER GARNISH	Not Necessary	72.40 FL	*- FL
39	2		*TAILGATE STOPPER	Necessary	49.20 FL	*49.20 FL
40	1		*TAILGATE INNER BOARD	Torn	240.00 FL	*160.00 FL
41	1		*TAILGATE WEATHERSTRIP	Cut	395.00 FL	*395.00 FL
42	1		*TAILGATE WEATHERSTRIP PROTECTOR	Bent	217.00 FL	*217.00 FL
43	1		*TAILGATE INNER LOCK	Damaged	340.00 FL	*340.00 FL
44	1		*TAILGATE LOCK MOTOR	Not Necessary	545.00 FL	*- FL
45	1		*TAILGATE LOWER LOCK	Not Necessary	105.00 FL	*- FL
46	2		*TAIL LAMP	Cracked	750.00 FL	*750.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAIL LAMP PANEL	O/s Dented	700.00 FL	*350.00 FL
48	2		*TAILLAMP LOWER GARNISH	Deformed	334.00 FL	*334.00 FL
49	2		*TAILLAMP LOWER GARNISH RETAINER	Not Necessary	130.00 FL	*- FL
50	1		*REAR BUMPER	Deformed	479.00 FL	*479.00 FL
51	2		*REAR BUMPER NUT COVER	Not Necessary	58.00 FL	*- FL
52	1		*REAR BUMPER STEP PANEL	Bent	398.00 FL	*398.00 FL
53	2		*REAR BUMPER SIDE RETAINER	Necessary	110.00 FL	*110.00 FL
54	1		*REAR END PANEL (EXTEND)	Repair	295.00 FL	*- FL
55	1		*REAR END PANEL (INNER)	Dented	871.00 FL	*871.00 FL
56	1		*REAR END PANEL (OUTER)	Dented	597.00 FL	*597.00 FL
57	1		*REAR FLOOR PANEL	Repair	1,960.00 FL	*- FL
58	1		*REAR FLOOR PANEL MAT	Not Necessary	1,359.00 FL	*- FL
59	1		*REAR SPARE TYRE HOLDER BRACKET	Not Necessary	380.00 FL	*- FL
60	1		*REAR SPARE TYRE HOLDER BOLT	Not Necessary	60.00 FL	*- FL
61	1		*REAR EXHAUST PIPE	Not Necessary	1,410.00 FL	*- FL
62	2		*REAR EXHAUST MOUNTING	Not Necessary	116.00 FL	*- FL
63	1		*REAR EXHAUST BRACKET	Not Necessary	90.00 FL	*- FL
64	1		*FRONT NUMBER PLATE	Buckled	50.00 FS	*50.00 FS
65	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
66	1		*SET FRONT GRILLE (UPPER) CLIP	Necessary	30.00 FS	*20.00 FS
67	1		*SET FRONT GRILLE (LOWER) CLIP	Necessary	30.00 FS	*20.00 FS
68	1		*FRONT GRILLE UPPER COVER GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
69	1		*SET FRONT GRILLE CENTER COVER GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
70	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	60.00 FS	*- FS
71	1		*SET WIPER PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
72	1		*BONNET SEALANT	Not Necessary	150.00 FS	*- FS
73	1		*COOLANT	Necessary	60.00 FS	*40.00 FS
74	1		*REAR NUMBER PLATE	Deformed	50.00 FS	*50.00 FS
75	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
76	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*20.00 FS
77	1		*SET TAILLAMP LOWER GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
78	1		*SET TAILGATE CENTER MOULDING CLIP	Necessary	30.00 FS	*20.00 FS
79	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
80	1		*SET TAILGATE OUTER MOULDING CLIP	Repeated	50.00 FS	*- FS
81	1		*SET TAILGATE CORNER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
82	1		*SET TAILGATE TOP TRIM CLIP	Not Necessary	50.00 FS	*- FS
83	1		*SET TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
84	1		*TAIL GATE STICKER 8 PAX	Necessary	50.00 FS	*15.00 FS
85	1		*TAIL GATE STICKER 70KM/H	Necessary	30.00 FS	*15.00 FS
86	1		*TAIL GATE STICKER CHINESE WORDING	Necessary	80.00 FS	*20.00 FS
87	1		*TAIL GATE STICKER AR SPECAIL TYPE	Necessary	120.00 FS	*20.00 FS
88	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
89	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
90	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*40.00 FS
91	1		*REAR END PANEL (EXTEND) SEALANT	Necessary	150.00 FS	*40.00 FS
92	1		*REAR FLOOR PANEL TOP BOARD (WOODEN) SPECAIL TYPE	Cracked	800.00 FS	*380.00 FS
93	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
94	1		*REVERSE CAMERA	Damaged	550.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	41,335.70	23,395.00
- List Item Discount on L Items 25.00/25.00% (\$)	9,496.43	5,466.25
Total Parts (\$)	31,839.27	17,928.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
6	REMOVE AND REFIX TURBO COOLER	New	120.00	0.00
7	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
8	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
9	PANEL BEATING AND REPLACE PARTS	New	2,200.00	1,200.00
10	SPRAY PAINTING TO AFFECTED AREA	New	2,000.00	1,000.00
11	WIRNING BULB CHECKING	New	80.00	30.00
12	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
13	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
14	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
15	REMOVE AND REFIX REAR FLOOR TOP BOARD (WOODEN)	New	500.00	100.00
16	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
17	REAR CHASSIS ALIGNMENT	New	250.00	0.00
18	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	50.00
19	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (S\$)			9,040.00	4,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >