

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 5699G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,148.00	1,148.00
2	REAR BUMPER SIDE HOLDER @\$75.00	NOT NECESSARY	150.00	-
2	REAR BUMPER REFLECTOR @\$85.00	NOT NECESSARY	170.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	632.00	-
1	REAR BUMPER LOWER GARNISH	DEFORMED	395.00	395.00
1	REAR BUMPER CENTRE GUIDE	CRACKED	185.00	185.00
2	REVERSE SENSOR @\$200.00	DAMAGED	400.00	400.00
1	BOOTLID	TO REPAIR SEE LABOUR	1,450.00	-
1	BOOTLID LOCK	NOT NECESSARY	385.00	-
1	BOOTLID WEATHERSTRIPE	NOT NECESSARY	319.00	-
1	VOLKSWAGEN LOGO	NECESSARY	85.00	85.00
1	JETTA EMBLEM	NECESSARY	78.00	78.00
1	TSI EMBLEM	NECESSARY	55.00	55.00
2	BOOTLID REFLECTOR @\$365.00	NOT NECESSARY	730.00	-
	LESS 10% DISCOUNT		-	-234.60
			6,182.00	2,111.40
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOTLID.		600.00	300.00
	SPRAY PAINTING.		600.00	500.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
			1,350.00	880.00
	GRAND TOTAL		7,562.00	3,021.40

Report Ref No. CS/SMO22000197/Avf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,400.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO22000197/Avf3n2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.