

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22000204/BTF3N2**Date:** 01/06/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001433317

Claimant Vehicle No : SKN7393R**Insured Vehicle No :** SDN9219G

Date of Loss: 06/01/2022

Nature of Claim: TP Claim No: 267850

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKN7393R**

Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)

Engine No: HR16944390B

Reg. Date: 14/07/2014 (Man. Year: 2014)

Chassis No: MNTBBAB17Z0019229

Colour: Red

Odometer: 21162 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R16

Rear Tyre Size: 195/60R16

Front Left Side: Falken 5 mm

Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm

Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,109.56	5,170.39	4,939.17	48.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,910.00	2,060.00	2,850.00	58.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,019.56	7,230.39	7,789.17	51.86
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	15,019.56	5,800.00	9,219.56	61.38
+ GST 7.00/7.00% (S\$)	1,051.37	406.00	645.37	61.38
Nett Amount (S\$)	16,070.93	6,206.00	9,864.93	61.38

INSPECTION

Date of Assignment: 06/01/2022

Date Inspected: 07/01/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jan 2022)

Parts: 143 NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKN7393R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,163.80 FL	*850.90 FL
2	1		*BOOTLID UPPER CHROME MOULDING	Not Necessary	185.70 FL	*- FL
3	1		*BOOTLID LOWER CHROME MOULDING	Not Necessary	81.70 FL	*- FL
4	1		*BOOTLID CENTRE EMBLEM	Necessary	46.90 FL	*46.90 FL
5	1		*BOOTLID SYLPHY EMBLEM	Necessary	87.00 FL	*75.20 FL
6	1		*BOOTLID XTONIC CVT EMBLEM	Necessary	57.70 FL	*57.70 FL
7	1		*BOOTLID RH LAMP	Not Damaged	141.80 FL	*- FL
8	1		*BOOTLID LH LAMP	Not Damaged	141.80 FL	*- FL
9	1		*BOOTLID LOCK	Jammed	64.50 FL	*64.50 FL
10	1		*BOOTLID LOCK CATCH	Not Damaged	57.60 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Distorted	87.30 FL	*87.30 FL
12	1		*BOOTLID RH HINGE	Not Damaged	88.10 FL	*- FL
13	1		*BOOTLID LH HINGE	Not Damaged	88.10 FL	*- FL
14	1		*BOOTLID INNER TRIM	Not Damaged	185.40 FL	*- FL
15	1		*REAR BUMPER	Dented	637.00 FL	*637.00 FL
16	1		*REAR BUMPER RH REFLECTOR	Broken	55.30 FL	*55.30 FL
17	1		*REAR BUMPER LH REFLECTOR	Broken	55.30 FL	*55.30 FL
18	1		*REAR BUMPER RH RETAINER	Necessary	51.30 FL	*40.00 FL
19	1		*REAR BUMPER LH RETAINER	Necessary	51.30 FL	*40.00 FL
20	1		*REAR BUMPER CENTRE INNER SPONGE	Broken	56.00 FL	*56.00 FL
21	1		*REAR BUMPER RH INNER SPONGE	Broken	105.30 FL	*105.30 FL
22	1		*REAR BUMPER LH INNER SPONGE	Broken	105.30 FL	*105.30 FL
23	1		*REAR BUMPER RH BRACKET	No such part	57.80 FL	*- FL
24	1		*REAR BUMPER LH BRACKET	No such part	57.80 FL	*- FL
25	1		*END PANEL	Dented	428.60 FL	*428.60 FL
26	1		*END PANEL INNER GARNISH	Broken	91.80 FL	*91.80 FL
27	1		*END PANEL ANTENNA SENSOR	Broken	199.20 FL	*68.90 FL
28	1		*RH TAILLAMP	Broken	441.00 FL	*397.60 FL
29	1		*LH TAILLAMP	Broken	441.00 FL	*397.60 FL
30	1		*REAR RH FENDER	Not Damaged	1,387.50 FL	*- FL
31	1		*REAR RH FENDER INNER TRIM	Broken	417.80 FL	*297.50 FL
32	1		*REAR LH FENDER	Bent	1,387.50 FL	*703.40 FL
33	1		*REAR LH FENDER INNER TRIM	Broken	417.80 FL	*325.00 FL
34	1		*SPARE TYRE PANEL TOP COVER	Broken	421.20 FL	*280.00 FL
35	1		*EXHAUST SILENCER	Not Damaged	890.20 FL	*- FL
36	1		*EXHAUST SILENCER GASKET	Not Necessary	55.00 FL	*- FL
37	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	70.00 FS	*30.00 FS
38	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
39	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS
40	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
41	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
42	1		*SET REAR FENDER RH INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
43	1		*SET REAR FENDER LH INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
44	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
45	1		*REAR RH FENDER JOINT SEALANT	Not Necessary	60.00 FS	*- FS
46	1		*REAR LH FENDER JOINT SEALANT	Necessary	60.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					11,138.40	5,697.10
- List Item Discount on L Items 10.00/10.00% (S\$)					1,028.84	526.71
Total Parts (S\$)					10,109.56	5,170.39
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,800.00	1,000.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,500.00	800.00
3	CHECK ALL WIRING AND ALL LIGHTING SYSTEM	New	100.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	150.00	0.00
5	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	120.00	80.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
7	REMOVE AND REPLACE REAR BUMPER INNER TRIMS AD BOARDS TO ASSIST REPAIR	New	220.00	0.00
8	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
9	REMOVE AND REINSTALL FUEL TANK,PIPES AND SENSORS TO ASSIST REPAIR	New	180.00	0.00
10	REMOVE AND REINSTALL ROOF LINING,SEATS AND CARPET TO ASSIST REPAIR	New	400.00	0.00
11	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	120.00	0.00
Gross Labour Cost (\$\$)			4,910.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >