4/22/22, 3:46 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22000207/VVY3S2

22/04/2022 Date:

**REFERENCE** 

China Taiping Insurance (Singapore) Handling Insurer:

Policy No:

DMCVSN00056932100

**Claimant Vehicle** 

Pte. Ltd. **SLU8640Y** 

**Insured Vehicle** 

**GBL1558P** 

No:

No:

Date of Loss:

28/12/2021

Nature of Claim: TP Claim

No:

SNM21D207683/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLU8640Y** Reg No:

SEAT LEON ST, 999cc (A) Make & Model:

Reg. Date: 15/12/2017 (Man. Year: 2017)

Odometer:

Engine No:

Chassis No:

VSSZZZ5FZJR047542

CHZ575847

34588 km

Colour: Grey

**Engine Capacity:** 999 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Rear Left Side: Michelin 7 mm Michelin 7 mm Rear Right Side: Michelin 7 mm Front Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,789.92	12,447.92	13,342.00	51.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,660.00	4,290.00	5,370.00	55.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,449.92	16,737.92	18,712.00	52.78
+ GST 7.00/7.00% (S\$)	2,481.49	1,171.65	1,309.84	52.78
Nett Amount (S\$)	37,931.41	17,909.57	20,021.84	52.78

**INSPECTION** 

Date of Assignment: 18/01/2022

Vertex Euro Motors Pte Ltd (HQ)

3 UBI ROAD 4 Date Inspected: 07/01/2022 Inspected At:

Singapore 408608

Estimated Period of Repair: 6.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/22/22, 3:46 PM Adjuster Report

## **REPAIR DETAILS**

## Reference

Part Source: (Last Synchronised: 22 Apr 2022)

Parts: N/A SEAT LEON ST 999cc (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU8640Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*BUMPER REINF RR	Dented	700.00 F	*700.00 F
<u>.</u>	1	*BUMPER BKT RR LH OTR	Serviceable	50.00 F	*- F
	1	*BUMPER BKT RR RH OTR	Serviceable	50.00 F	*- F
	1	*BUMPER BKT LH RR INN	Cut	70.00 F	*70.00 F
	1	*BUMPER BKT RR RH INN	Cut	70.00 F	*70.00 F
;	1	*BUMPER SPONGE RR	Cut	80.00 F	*80.00 F
•	1	*BUMPER STRIP RR CTR	Serviceable	80.00 F	*- F
}	1	*BUMPER STRIP RR	Cut	70.00 F	*70.00 F
)	1	*BUMPER RR	Dented	1,600.00 F	*1,600.00 F
0	1	*BUMPER TOW CAP	Distorted	40.00 F	*40.00 F
1	1	*B/REFLECTOR LH	Serviceable	60.00 F	*- F
2	1	*B/REFLECTOR RH	Serviceable	60.00 F	*- F
13	2	*CLIP	Necessary	6.00 F	*6.00 F
14	1	*COVER - REVERSE CAMERA	Serviceable	110.00 F	*- F
15	1	*COVER - REVERSE CAMERA	Serviceable	150.00 F	*-F
16	1	*BUMPER SPOILER RR	Cut	570.00 F	*570.00 F
17	1	*LID RR	Repair	2,550.00 F	*-F
18	1	*RUBBER - LID REAR	Serviceable	300.00 F	*-F
19	1	*LETTERING LEON	Necessary	50.00 F	*50.00 F
20	1	*T/LAMP LH OTR	Serviceable	410.00 F	30.001 *-F
21	<u>'</u> 	*T/LAMP RH OTR	Serviceable	410.00 F	*-F
22	1	*T/LAMP LH INN	Serviceable	400.00 F	*-F
23	1	*T/LAMP RH INN	Serviceable	400.00 F	*-F
23 24	1	*NUMBER PLATE REAR	Dented	80.00 F	*80.00 F
25	1	*NO PLANT REAR	Not Necessary	0.00 F	*-F
	I	(NPA)	•		
26	1	*NUMBER PLATE FRONT	Dented	80.00 F	*80.00 F
27	1	*BUMPER REINF FRT	Cut	780.00 F	*780.00 F
28	1	*BUMPER BKT FRT LH	Serviceable	120.00 F	*-F
29	1	*BUMPER BKT FRT RH	Serviceable	120.00 F	*- F
30	1	*BUMPER FRT	Cut	1,650.00 F	*1,650.00 F
31	1	*BUMPER TOW CAP FRT	Serviceable	105.00 F	*- F
32	1	*BUMPER GRILLE FRT	Cut	200.00 F	*200.00 F
33	1	*F/LAMP GRILLE LH	Serviceable	130.00 F	*- F
34	1	*F/LAMP GRILLE RH	Serviceable	130.00 F	*- F
35	1	*BUMPER SPOILER FRT BIG	Cut	640.00 F	*640.00 F
36	1	*BUMPER SPOILER FRT SMALL	Cut	500.00 F	*500.00 F
37	1	*BONNET	Serviceable	1,700.00 F	*- F
88	1	*F/LAMP LH	Serviceable	360.00 F	*- F
39	1	*F/LAMP RH	Serviceable	360.00 F	*- F
10	1	*H/LAMP LH	Cracked	1,450.00 F	*1,450.00 F
1	1	*H/LAMP RH	Cracked	1,450.00 F	*1,450.00 F
2	1	*DIRT DEFLECTOR FRT	Serviceable	125.00 F	*- F
  3	 1	*RAD GRILLE FRT	Cut	580.00 F	*580.00 F
14	1	*RAD GRILLE COVER FRT	Cut	225.00 F	*225.00 F
45	1	*RAD GRILLE LOGO S	Cut	100.00 F	*100.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	7		*CLIP	Not Necessary	7.00 F	*- F
47	1		*RADIATOR COVER LOWER	Serviceable	50.00 F	*- F
48	1		*ADD RADIATOR	Serviceable	460.00 F	*- F
49	1		*RADIATOR	Serviceable	460.00 F	*- F
50	1		*RAD AIR GUIDE LH	Cut	45.00 F	*45.00 F
51	1		*RAD AIR GRILLE RH	Serviceable	45.00 F	*- F
52	2		*RAD BUSH	Serviceable	90.00 F	*- F
53	1		*RADIATOR FAN	Serviceable	820.00 F	*- F
54	1		*AIR DUCT TOP-SUPPORT PANEL	Serviceable	100.00 F	*- F
55	1		*AIR DUCT COVER - SUPPORT PANEL	Serviceable	55.00 F	*- F
56	1		*AIR DUCT RR - SUPPORT PANEL	Serviceable	40.00 F	*- F
57	1		*HOSE - AIR DUCT SMALL	Serviceable	65.00 F	*- F
58	1		*A/C CONDENSER W DRYER	Serviceable	500.00 F	*- F
59	1		*SUPPORT PANEL	Serviceable	620.00 F	*- F
60	1		*H/LAMP BKT LH	Cut	60.00 F	*60.00 F
61	1		*H/LAMP BKT RH	Cut	60.00 F	*60.00 F
62	1		*S/PANEL BKT LH	Cut	230.00 F	*230.00 F
63	1		*S/PANEL BKT RH	Cut	230.00 F	*230.00 F
64	1		*BONNET HINGE LH	Serviceable	100.00 F	*- F
65	1		*BONNET HINGE RH	Serviceable	100.00 F	*- F
66	1		*SEAL FILTER PIECE LH	Serviceable	145.00 F	*- F
67	1		*SEAL FILTER PIECE RH	Serviceable	145.00 F	*- F
68	2		*P/SENSOR RR LH & RH	Serviceable	640.00 F	*- F
69	2		*P/SENSOR FRT OTR CTR	Serviceable	640.00 F	*- F
70	4		*O-RING - P/SENSOR	Necessary	20.00 F	*20.00 F
71	1		*BKT - P/SENSOR NO.1	Necessary	90.00 F	*90.00 F
72	1		*BKT - P/SENSOR NO.2	Necessary	90.00 F	*90.00 F
73	1		*BKT - P/SESNOR NO.3	Necessary	90.00 F	*90.00 F
74	1		*BKT - P/SENSOR NO.4	Necessary	90.00 F	*90.00 F
75	1		*SUNDRIES	Necessary	120.00 FS	*40.00 FS
76	1		*AIR FREIGHT CHARGES	Necessary	411.92 F	*411.92 F
F=Fra	anchise	part. S=SpcN	ett.	-		
				Total Parts (S\$)	25,789.92	12,447.92

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	LABOUR TO REMOVE, REINSTALL AND CHECK FRONT WIRENESS.	New	180.00	180.00
2	LABOUR TO REPLACE, REPAIR FRT BUMPER, RR BUMPER, RR LID, BONNET, SUPPORT PANEL, RR IRON PANEL.	New	5,500.00	1,950.00
3	LABOUR TO RESPRAY FRT BUMPER, RR BUMPER, LID RR, BONNET, RR IRON PANEL.	, New	3,500.00	1,800.00
4	LABOUR TO RENEW AND TRANSFER REAR PARKING AID.	New	180.00	180.00
5	LABOUR TO REFILL VACUUM AND REFILL A/C GAS.	New	120.00	0.00
6	LABOUR TO CARRY OUT DIAGNOSTIC CHECK.	New	180.00	180.00
	Gross Labour	Cost (S\$)	9,660.00	4,290.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >