

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000210/KGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070007669
Claimant Vehicle No :	SMA2144X	Insured Vehicle No :	GY2657C
Date of Loss:	04/01/2022	Nature of Claim:	TP
		Claim No:	3937578898SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA2144X	Engine No:	2ZR8433209
Make & Model:	TOYOTA C-HR, 1.8 (A)	Chassis No:	ZYX102118974
Reg. Date:	30/05/2018 (Man. Year: 2018)	Odometer:	281482 km
Colour:	Metallic Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Tourador 8 mm	Rear Left Side:	Tourador 8 mm
Front Right Side:	Tourador 8 mm	Rear Right Side:	Tourador 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,812.00	3,171.25	640.75	16.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	665.00	295.00	30.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,772.00	3,836.25	935.75	19.61
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	4,772.00	3,000.00	1,772.00	37.13
+ GST 7.00/7.00% (S\$)	334.04	210.00	124.04	37.13
Nett Amount (S\$)	5,106.04	3,210.00	1,896.04	37.13
+ Car Rental (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,512.00		

INSPECTION

Date of Assignment:	06/01/2022	
Date Inspected:	06/01/2022	Inspected At: Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET LOCK	Repair	105.00 FL	*- FL
2	1		*FRONT BONNET REINFORCEMENT	Repair	296.00 FL	*- FL
3	1		*FRONT BUMPER ABSORBER FOAM	Serviceable	80.00 FL	*- FL
4	1		*FRONT RADAR SENSOR	Shorted	1,535.00 FL	*1,295.00 FL
5	1		*FRONT BONNET (CARBON FIBER)	Cracked	1,300.00 FS	*1,200.00 FS
6	1		*FRONT BUMPER	Cracked	1,000.00 FS	*1,000.00 FS
					Sub Total (\$)	4,316.00 3,495.00
					- List Item Discount on L Items 25.00/25.00% (\$)	504.00 323.75
					Total Parts (\$)	3,812.00 3,171.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE ,REFIX & READJUST FRONT ACCIDENT AREAS & ETC	New	400.00	250.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISING MATERIALS AT FRONT BUMPER & ETC	New	300.00	220.00
3	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	15.00
4	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	180.00	180.00
Gross Labour Cost (S\$)			960.00	665.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >