

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000214/APA3Q2**Date:** 06/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070180491
Claimant Vehicle No :	SKW9495U	Insured Vehicle No :	SLA3355J
Date of Loss:	01/01/2022	Nature of Claim:	TP
		Claim No:	0915371530SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW9495U	Engine No:	P520328561
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Chassis No:	JM6BM42A8G0323536
Reg. Date:	23/11/2015 (Man. Year: 2015)	Odometer:	181826 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,847.28	14,283.92	10,563.36	42.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,380.00	3,950.00	2,430.00	38.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,227.28	18,233.92	12,993.36	41.61
Approved Total (Overridden) (S\$)		14,500.00		
Nett Amount (S\$)	31,227.28	14,500.00	16,727.28	53.57
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		15,602.00		
Global Sum Settlement (S\$)		15,600.00		

INSPECTION

Date of Assignment:	04/01/2022		
Date Inspected:	04/01/2022	Inspected At:	SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	13.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$45,000.00 (est) less LTA Rebate: \$28,903.00 (est) = Nett Value
:\$16,097.00 (est)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,264.40 FL	*1,083.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	498.10 FL	*498.10 FL
3	1		*FRONT BUMPER REINFORCEMENT GARNISH	Cracked	215.60 FL	*215.60 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	285.60 FL	*- FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	173.20 FL	*173.20 FL
6	2		*FRONT BUMPER FOG LAMP	Cracked	953.80 FL	*702.60 FL
7	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	196.80 FL	*- FL
8	2		*FRONT BUMPER FOG LAMP HOUSING COVER	Not Necessary	36.80 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Deformed	308.50 FL	*83.00 FL
10	2		*FRONT BUMPER LOWER GRILLE SIDE COVER	Missing	43.60 FL	*43.60 FL
11	1		*FRONT BUMPER TOW COVER	Deformed	46.60 FL	*46.60 FL
12	1		*FRONT BUMPER UNDER COVER	Torn	198.00 FL	*198.00 FL
13	1		*FRONT GRILLE	Cracked	870.50 FL	*610.00 FL
14	2		*FRONT GRILLE OUTER CHROME	Cracked	651.60 FL	*370.00 FL
15	1		*FRONT GRILLE LOGO	Necessary	104.90 FL	*45.00 FL
16	1		*FRONT GRILLE TOP PANEL GARNISH	Deformed	398.40 FL	*398.40 FL
17	2		*FRONT GRILLE SIDE GUARD GARNISH	Not Necessary	271.20 FL	*- FL
18	1		*BONNET	Dented	1,259.40 FL	*1,259.40 FL
19	1		*BONNET LOCK	Damaged	189.20 FL	*189.20 FL
20	1		*BONNET RUBBER	Not Necessary	61.80 FL	*- FL
21	2		*FRONT HEADLAMP	Cracked	3,246.60 FL	*3,246.60 FL
22	1		*FRONT SUPPORT PANEL	Cracked	980.10 FL	*593.00 FL
23	1		*FRONT SUPPORT TOP PANEL	Bent	417.60 FL	*215.00 FL
24	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	159.30 FL	*159.30 FL
25	1		*FRONT BRACE PANEL	Bent	98.40 FL	*98.40 FL
26	1		*AIR CON CONDENSER	Dented	1,544.30 FL	*1,063.00 FL
27	1		*LH FRONT FENDER	Repair	459.40 FL	*- FL
28	1		*LH FRONT FENDER INNER SHIELD	Not Necessary	175.10 FL	*- FL
29	1		*REAR BUMPER	Deformed	1,023.90 FL	*1,023.90 FL
30	1		*REAR BUMPER REINFORCEMENT	Dented	582.40 FL	*582.40 FL
31	1		*REAR BUMPER TOW COVER	O/S Missing	117.20 FL	*58.60 FL
32	1		*REAR BUMPER REFLECTOR	O/S Cracked	309.60 FL	*154.80 FL
33	2		*REAR BUMPER SIDE RETAINER	Cracked	150.20 FL	*150.20 FL
34	1		*REAR END PANEL OUTER	Dented	687.40 FL	*530.00 FL
35	1		*REAR END PANEL INNER	Not Necessary	549.60 FL	*- FL
36	1		*REAR END PANEL TOP GARNISH	Cracked	398.40 FL	*168.00 FL
37	1		*REAR WEATHERSTRIPE	Cut	172.80 FL	*172.80 FL
38	1		*REAR BOOTLID	Dented	1,645.50 FL	*1,026.00 FL
39	1		*REAR BOOTLID LOCK	Damaged	320.10 FL	*186.00 FL
40	1		*REAR BOOTLID LAMP	O/S Cut	1,174.20 FL	*385.00 FL
41	1		*REAR BOOTLID EMBLEM LOGO	Necessary	66.40 FL	*66.40 FL
42	1		*REAR BOOTLID EMBLEM MAZDA 3	Necessary	31.40 FL	*31.40 FL
43	1		*REAR BOOTLID EMBLEM SKYACTIC	Necessary	32.40 FL	*32.40 FL
44	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	198.70 FL	*- FL
45	1		*REAR TAILLAMP	O/S Cut	2,091.20 FL	*867.00 FL
46	2		*REAR TAILLAMP INNER PANEL	Repair	974.40 FL	*- FL
47	1		*RH REAR FENDER	Repair	1,698.10 FL	*- FL
48	2		*REAR FENDER INNER TRIM	Not Necessary	1,378.80 FL	*- FL
49	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
50	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
51	1		*FRONT TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
52	1		*FRONT BUMPER TOP PANEL GARNISH RIVET	Necessary	60.00 FS	*20.00 FS
53	1		*AIR CON GAS	Necessary	120.00 FS	*50.00 FS
54	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	60.00 FS	*- FS
55	1		*LH FRONT FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
57	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
58	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
59	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
60	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
61	1		*REAR BOOTLID INNER TRIM	Not Necessary	60.00 FS	*- FS
62	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
63	1		*REAR SPARE TYRE TOP BOARD	Deformed	331.40 FL	*249.00 FL
64	1		*REAR FLOOR PANEL TOOLS SPONGE	Cracked	391.20 FL	*305.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					30,734.10	17,739.90
- List Item Discount on L Items 20.00/20.00% (S\$)					5,886.82	3,455.98
Total Parts (S\$)					24,847.28	14,283.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	2,800.00	2,000.00
2	LABOUR FOR SPRAY PAINTING	New	1,800.00	1,500.00
3	WIRING CHECK	New	80.00	60.00
4	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS	New	300.00	80.00
5	LABOUR FOR REMOVE & RENEW REAR WINDSCREEN GLASS	New	150.00	0.00
6	LABOUR FOR REPAIR & STRAIGHTEN LH FRONT /BOTH REAR CHASSIS FRAME	New	600.00	0.00
7	LABOUR FOR REMOVE & RENEW AIR CON CONDENSER ,TOP UP & VACUUM AIR CON GAS	New	200.00	120.00
8	LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING	New	200.00	60.00
9	TO REMOVE REVERSE SENSOR	New	100.00	50.00
10	TO REMOVE AND REFIT UPHOLSTERY	New	150.00	80.00
Gross Labour Cost (S\$)			6,380.00	3,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >