

ASS. REC. BY: Taught

REF: CS/ASUM 22 000216/T1143.

ASSIGNMENT

COE 2027 Sep.
2007, Oct.

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 954K. X
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA /-PR Seen: _____ Consistent? : Yes or No
Est Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMS42A Yr Regn: _____
Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Volkswagen Golf GTI c.c. 1984
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 223648 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WVWZZZ/KZ74040342
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 225/40R18.
R: 7 -
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 10/1/22 @ 540pm
Survey held at TSC Auto.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____
Rep. Format : _____
Lump Sum / L.B.A. (\$) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Visual. (\$)

Survey Fee: _____
Transportation: _____
S + RS. \$I
Photos
Others

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMS42A Volkswagen GTI

			Estimated	
No	Qty	Parts Description	Parts	Price
1	1	Rear bumper assy	\$	1,271.20 <i>de ✓</i>
2	2	Rear bumper bracket	\$	86.40 <i>x</i>
3	2	Rear bumper retainer	\$	89.60 <i>x</i>
4	1	Rear bumper reinforcement	\$	378.90 <i>bt ✓</i>
5	1	Rear bumper inner beam	\$	189.70 <i>x</i>
6	1	Rear tailgate assy	\$	1,632.10 <i>bt ✓</i>
7	1	Rear tailgate centre logo	\$	128.50 <i>x</i>
8	1	Rear tailgate lock mechanism	\$	191.30 <i>bt</i>
9	1	Rear tailgate lock catch	\$	86.40 <i>x</i>
10	2	Rear tailgate damper	\$	367.70 <i>x</i>
11	1	Rear tailgate weatherstrip	\$	188.10 <i>twi ✓</i>
12	1	Rear tailgate left taillamp	\$	445.20 <i>x</i>
13	1	Rear tailgate right taillamp	\$	445.20 <i>x</i>
14	1	Rear tailgate inner board	\$	378.60 <i>x</i>
15	1	Rear left taillamp	\$	698.20 <i>x</i>
16	1	Rear right taillamp	\$	698.20 <i>x</i>
17	1	Rear end lower panel	\$	956.60 <i>Rx</i>
18	1	Rear end lower panel top garnish	\$	128.10 <i>de ✓</i>
19	1	Rear spare tyre top board	\$	298.60 <i>x</i>
20	1	Rear floor panel	\$	1,245.30 <i>x</i>
21	1	Rear exhaust heat shield	\$	296.80 <i>x</i>
22	1	Rear windscreen glass moulding	\$	289.10 <i>nei ✓</i>
23	1	Rear exhaust muffler assy	\$	1,602.80 <i>SN 300 local repair</i>
24	2	Rear exhaust muffler rubber mounting	\$	83.60 <i>x n n</i>
			\$	12,176.20
Less 10%			\$	1,217.62
			\$	10,958.58

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMS42A Volkswagen GTI

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	10	Rear bumper clips	\$	50.00 30 new ✓
2	6	Rear end lower panel top garnish clips	\$	30.00 10 new ✓
3	1	Rear bumper lower spoiler	\$	1,200.00 de ✓ 450
4	1	Rear bumper lower spoiler sealant	\$	100.00 40 new ✓
5	10	Rear bumper lower spoiler clips	\$	50.00 X ny
6	1	Rear bumper right side spoiler	\$	450.00 X ny
7	1	Rear bumper left side spoiler	\$	450.00 X ny
8	1	Rear end lower panel sealant	\$	120.00 X ny.
9	1	Rear floor panel sealant	\$	150.00 X ny
10	1	Rear floor panel insulator pad	\$	180.00 X ny
11	8	Rear tailgate inner board clips	\$	40.00 X ny.
12	2	Rear bumper reverse sensor	\$	500.00 20 new ✓
13	1	Rear windscreen glass sealant	\$	100.00 40 new ✓
14	1	Rear no plate with garnish	\$	100.00 45 new ✓
			\$	<u>3,520.00</u>
Total parts			\$	14,478.58

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMS42A Volkswagen GTI

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,400.00 600
2	To putty and spray painting rear portion.	\$ 1,400.00 700
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear bootlid lock mechanism.	\$ 80.00 60
5	To remove and install rear exhaust muffler assy.	\$ 120.00 60
6	To remove and install rear seat, inner garnish and trim to facilitate the repair.	\$ 180.00 60
7	To apply anti rust proofing to rear affected area.	\$ 140.00 30
8	To remove and install rear bumper reverse sensor.	\$ 80.00 30
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 120
10	Towing service.	\$ 100.00 X 100
Total labour :		\$ 3,690.00

Tanpin 97495749

Total parts : \$ 14,478.58

Total labour : \$ 3,690.00

Total repair cost : \$ 18,168.58

WP' 10/1/22 254000
 1/5 Resurvey after repair
 05 days
 Tanpin @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: