

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22000222/AES3Q2**Date:** 15/08/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SMQ8333T **Insured Vehicle No :** SLQ4227E

Date of Loss: 03/01/2022 Nature of Claim: TP Claim No: MFL2022D0000202

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ8333T**

Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11AD2873

Reg. Date: 25/10/2019 (Man. Year: 2018) Chassis No: GF7W0600830

Colour: Red Odometer: 28908 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,893.86	2,665.58	2,228.28	45.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,080.00	1,520.00	58.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,493.86	3,745.58	3,748.28	50.02
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	7,493.86	3,000.00	4,493.86	59.97
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,307.45		

INSPECTION

Date of Assignment: 04/01/2022

Date Inspected: 04/01/2022 Inspected At:

Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2022)
Parts:	M1-SUV	mitsubishi outlander 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ8333T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,164.00 FL	*- FL
2	1		*TAILGATE CENTRE LOGO	Not Necessary	45.60 FL	*- FL
3	1		*TAILGATE OUTERLANDER EMBLEM	Necessary	85.20 FL	*85.20 FL
4	1		*TAILGATE MIVE EMBLEM	Necessary	85.20 FL	*85.20 FL
5	1		*REAR BUMPER	Deformed	1,209.60 FL	*981.00 FL
6	2		*REAR BUMPER SIDE HOLDER	Necessary	43.20 FL	*43.20 FL
7	1		*REAR BUMPER LOWER LIP	Deformed	650.00 FL	*420.00 FL
8	1		*REAR BUMPER LH REFLECTOR	Cut	105.60 FL	*105.60 FL
9	1		*REAR BUMPER TOP PROTECTOR	Bent	304.00 FS	*300.00 FS
10	1		*REAR LH BUMPER SIDE GARNISH	Not Necessary	96.00 FL	*- FL
11	1		*REAR LH LAMP	Cracked	650.00 FL	*565.00 FL
12	1		*REAR LH BUMPER IMPACT BRACKET	Dented	121.00 FL	*121.00 FL
13	2		*REAR BUMPER REVERSE SENSOR	Damaged	760.00 FS	*200.00 FS
					Sub Total (\$\$)	
					5,319.40	2,906.20
					- List Item Discount on L Items 10.00/10.00% (\$\$)	
					425.54	240.62
					Total Parts (\$\$)	
					4,893.86	2,665.58

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX INNER GARNISH	New	200.00	30.00
2	REMOVE & REFIX REVERSE SENSOR	New	200.00	50.00
3	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
4	RESPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,600.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >