

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22000223/KTY3N2**Date:** 26/01/2022**REFERENCE**

Insured/Claimant: COLIN FRANCIS ENRIQUEZ Policy No: DMPCSNW00114732100

Date of Loss: 05/01/2022

Nature of Claim: OD

Claim No: SNM22D200123/C01/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMX4572J**  
 Make & Model: MERCEDES-BENZ B200, 1.3 PROGRESSIVE (R18 LED) (A) Engine No: 28291480160396  
 Reg. Date: 18/07/2019 (Man. Year: 2019) Chassis No: WDD2470872J031673  
 Colour: Metallic Grey Odometer: 34235 km  
 Engine Capacity: 1332 cc  
 Market Value/New Car Price: S\$138,000.00  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/40R19 Rear Tyre Size: 225/40R19  
 Front Left Side: Falken 8 mm Rear Left Side: Falken 8 mm  
 Front Right Side: Falken 8 mm Rear Right Side: Falken 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,908.30	4,645.60	2,262.70	32.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,030.00	470.00	31.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,408.30</b>	<b>5,675.60</b>	<b>2,732.70</b>	<b>32.50</b>
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	7,908.30	5,175.60	2,732.70	34.55
<b>+ GST 7.00/7.00% (S\$)</b>	553.58	362.29	191.29	34.56
<b>Nett Amount (S\$)</b>	<b>8,461.88</b>	<b>5,537.89</b>	<b>2,923.99</b>	<b>34.55</b>

**INSPECTION**

Date of Assignment: 07/01/2022

Date Inspected: 07/01/2022 Inspected At:

Alan's United Auto Pte Ltd (HQ)  
Blk 7 Sin Ming Industrial Estate, #01-76  
Singapore 575642

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 Jan 2022)

**Parts:** 143 MERCEDES-BENZ B200 1.3 PROGRESSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMX4572J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA (WCP)	Bent	950.00 F	*950.00 F
2	1		*FRONT N/S BUMPER BRACKET (WCP)	Missing	8.00 F	*8.00 F
3	1		*FRONT BUMPER LOGO (WCP)	Necessary	55.00 F	*55.00 F
4	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	290.00 F	*- F
5	1		*FRONT BUMPER SPONGE (WCP)	Serviceable	97.00 F	*- F
6	1		*FRONT BUMPER UNDER COVER (WCP)	Serviceable	213.00 F	*- F
7	4		*FRONT BUMPER UNDER COVER RIVET (WCP)	Not Necessary	20.00 F	*- F
8	1		*FRONT N/S FOGLAMP COVER (WCP)	Missing	45.00 F	*45.00 F
9	1		*FRT N/S FOGLAMP SENSOR HOLDER (WCP)	Missing	12.00 F	*12.00 F
10	1		*FRT N/S FOGLAMP COVER SENSOR (WCP)	Missing	115.00 F	*115.00 F
11	1		*FRT N/S PARKING SENSOR (WCP)	Cracked	115.00 F	*115.00 F
12	1		*FRT N/S PARKING SENSOR SEAL (WCP)	Necessary	6.00 F	*6.00 F
13	1		*FRT N/S BUMPER RADAR SENSOR (WCP)	Serviceable	850.00 F	*- F
14	1		*N/S BUMPER RADAR SENSOR BRACKET (WCP)	Repair	125.00 F	*- F
15	1		*N/S HEADLAMP (WCP)	Cracked	1,500.00 F	*1,500.00 F
16	1		*N/S HEADLAMP ECU (WCP)	Serviceable	370.00 F	*- F
17	1		*FRONT N/S FENDER (WCP)	Bent	490.00 F	*490.00 F
18	1		*FRONT N/S FENDER BRACKET (WCP)	Bent	12.00 F	*12.00 F
19	1		*FRONT N/S FENDER INNER SUPPORT (WCP)	Serviceable	60.00 F	*- F
20	1		*FRT N/S FENDER LOWER SHIELD (WCP)	Serviceable	32.00 F	*- F
21	1		*FRT N/S FENDER INNER SHIELD (F)(WCP)	Cracked	170.00 F	*170.00 F
22	4		*FRT N/S INNER SHIELD CLIP (WCP)	Necessary	18.00 F	*18.00 F
23	1		*FRONT N/S SPORT RIM	Dented	800.00 FS	*800.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>6,353.00</b>	<b>4,296.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	555.30	349.60
<b>Total Parts (\$\$)</b>	<b>6,908.30</b>	<b>4,645.60</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM,DISGNOS & PROGRAMME	New	120.00	80.00
2	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	80.00	60.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	440.00
4	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	700.00	450.00
<b>Gross Labour Cost (\$)</b>			<b>1,500.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >