

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000224/UVY3N2**Date:** 25/02/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00107022104

**Claimant Vehicle No :** SMT3249X **Insured Vehicle No :** GBE1286K

Date of Loss: 04/01/2022 Nature of Claim: TP Claim No: SNM22D200121/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT3249X**

Make & Model: HONDA CIVIC, 1.6 VTI (A) Engine No: R16A12000722

Reg. Date: 26/04/2007 (Man. Year: 2007) Chassis No: JHMFD46207S200426

Colour: Silver Odometer: 228583 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,900.52	1,806.56	1,093.96	37.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,970.00	980.00	33.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,850.52</b>	<b>3,776.56</b>	<b>2,073.96</b>	<b>35.45</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,850.52</b>	<b>2,800.00</b>	<b>3,050.52</b>	<b>52.14</b>

INSPECTION

Date of Assignment: 07/01/2022

Date Inspected: 07/01/2022 Inspected At: Quan De Motor Trading  
BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY  
SINGAPORE 417883  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2022)
<b>Parts:</b> 143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMT3249X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented/Buckled	610.70 FL	*610.70 FL
2	1		*BOOTLID H LOGO	Necessary	28.80 FL	*28.80 FL
3	1		*BOOT LID CIVIC EMBLEM	Necessary	30.00 FL	*30.00 FL
4	1		*BOOT LID V-TEC EMBLEM	Necessary	31.00 FL	*31.00 FL
5	1		*BOOTLID REFLECTOR LH	Cracked	165.80 FL	*165.80 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	119.20 FL	*119.20 FL
7	1		*REAR BUMPER	Dented/Deformed	638.10 FL	*638.10 FL
8	1		*REAR BUMPER SIDE RETAINER LH	Bent	25.50 FL	*25.50 FL
9	1		*REAR END PANEL	Dented	306.10 FL	*306.10 FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	182.60 FL	*- FL
11	1		*TAILLAMP LH	Broken	265.50 FL	*265.50 FL
12	1		*REAR FENDER LH	Repair	791.10 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
14	1		*SET REAR REVERSE SENSOR	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,539.40</b>	<b>2,250.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	638.88	444.14
<b>Total Parts (\$)</b>	<b>2,900.52</b>	<b>1,806.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIX BOOTLID MECHANISM	New	100.00	60.00
4	TO REMOVE & REFIX CUSHION UPHOLSTERY	New	100.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	60.00
6	LABOUR FOR PANEL BEATING,WELDING & RENEW PARTS	New	1,200.00	900.00
7	SPRAY PAINTING	New	1,300.00	800.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,950.00</b>
				<b>1,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >