

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000226/AVCE2

Date: 09/05/2022

REFERENCE

Insured/Claimant:	TAN PECK HWEE	Policy No:	1900255667-01	
Date of Loss:	29/12/2021	Nature of Claim:	OD	Claim No: 1265463469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1701E		
Make & Model:	AUDI A1 SPORTBACK, 1.0 Advanced TFSI S-tronic (A)	Engine No:	DKJ046332
Reg. Date:	29/11/2019 (Man. Year: 2019)	Chassis No:	WAUZZZGB9LR008362
Colour:	Green	Odometer:	9096 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$101,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,986.00	6,289.60	3,696.40	37.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,342.00	3,102.00	3,240.00	51.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,328.00	9,391.60	6,936.40	42.48
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	15,728.00	8,791.60	6,936.40	44.10
+ GST 7.00/7.00% (\$\$)	1,100.96	615.41	485.55	44.10
Nett Amount (\$\$)	16,828.96	9,407.01	7,421.95	44.10

INSPECTION

Date of Assignment:	07/01/2022		
Date Inspected:	06/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,634.00 FS	*1,307.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	137.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER - LH	Not Necessary	100.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	211.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	167.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE PROFILE - LH	Not Necessary	36.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	107.00 FS	*- FS
8	1		*FRONT FENDER - LH	Dented	978.00 FS	*782.40 FS
9	1		*FRONT FENDER BRACE - LH	Not Necessary	54.00 FS	*- FS
10	1		*FRONT FENDER BRACKET - LH	Not Necessary	37.00 FS	*- FS
11	1		*FRONT FENDER BRACKET CENTER - LH	Not Necessary	14.00 FS	*- FS
12	1		*FRONT WHEEL HOUSING LINER	Not Necessary	0.00 FS	*- FS
13	1		*HEADLIGHT - LH	Chipped	4,288.00 FS	*3,430.40 FS
14	1		*LIFT CYLINDER - LH	Not Necessary	142.00 FS	*- FS
15	1		*LIFT CYLINDER HOSE	Not Necessary	59.00 FS	*- FS
16	1		*ALUMINIUM RIM - LH	Cut	962.00 FS	*769.60 FS
17	1		*WING MIRROR MOUNTING - LH	Not Necessary	588.00 FS	*- FS
18	1		*WING MIRROR CAP - LH	Not Necessary	130.00 FS	*- FS
19	1		*SIGNAL INDICATOR - LH	Not Necessary	92.00 FS	*- FS
20	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,986.00	6,289.60
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	280.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS WING MIRROR COVER	New	2,500.00	1,100.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO SUPPLY AND INSTALL PAINT WRAPPING (3M) (Supplementary)	New	280.00	280.00
Gross Labour Cost (\$\$)			6,342.00	3,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >