

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22000233/GPA3Q2
Date: 20/10/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900260946
Claimant Vehicle No :	SHD6484G	Insured Vehicle No :	SMR4949M
Date of Loss:	31/12/2021	Nature of Claim:	TP
		Claim No:	6472123501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6484G		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS102087
Reg. Date:	03/11/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FUX03573694
Colour:	Maroon	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,491.48	7,462.21	30,029.27	80.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,685.00	2,530.00	4,155.00	62.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	44,176.48	9,992.21	34,184.27	77.38
Approved Total (Overridden) (\$\$)		8,500.00		
Nett Amount (\$\$)	44,176.48	8,500.00	35,676.48	80.76
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	05/01/2022	
Date Inspected:	05/01/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	8.0 days	

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,REAR DOOR ,LH (DISC 25%)	Distorted	1,243.90 F	*932.93 F
2	1		*WEATHERSTRIP REAR DOOR LH (DISC 25%)	Jammed	174.40 F	*130.80 F
3	1		*PANEL SUB-ASSY ,FENDER REAR LH (DISC 25%)	Distorted	824.80 F	*618.60 F
4	1		*LINER REAR FENDER LH (DISC 25%)	Deformed	135.80 F	*101.85 F
5	1		*WHEEL DISC (DISC 25%)	Cut	1,555.10 F	*1,166.32 F
6	1		*CAP SUB-ASSY ,WHEEL (DISC 25%)	Cut	175.80 F	*131.85 F
7	1		*HUB & BEARING ASSY RH & LH (DISC 25%) (2 PCS)	Bent	554.20 F	*415.65 F
8	1		*ROOF HEADLINING ASSY (DISC 25%)	Crumpled	2,059.50 F	*1,544.63 F
9	1		*AIR BAG ASSY ROOF SIDE CURTAIN SHIELD LH (DISC 10%)	Activated	1,463.80 F	*1,317.42 F
10	1		*AIR BAG COMPUTER ASSY (DISC 10%)	Activated	1,083.80 F	*975.42 F
11	1		*TYRE (SN)	Cut	126.74 F	*126.74 F
12	1		*WIRE REAR DOOR LH	Not Necessary	206.70 F	*- F
13	1		*CARRIER SUB-ASSY,REAR AXLE RH	Not Necessary	802.70 F	*- F
14	1		*TAIL GATE PANEL SUB-ASSY ,BACK DOOR	Not Necessary	929.60 F	*- F
15	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB ASSY	Not Necessary	891.20 F	*- F
16	1		*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT DOOR	Not Necessary	52.30 F	*- F
17	1		*NAME PLATE (PRIUS) LUGGAGE COMPARTMENT DOOR	Not Necessary	52.30 F	*- F
18	1		*SPOILER SUB-ASSY REAR	Not Necessary	1,322.10 F	*- F
19	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
20	1		*BRACKET FR BUMPER	Not Necessary	99.80 F	*- F
21	1		*NUMBER PLATE	Not Necessary	35.00 F	*- F
22	1		*NUMBER PLATE FRAME	Not Necessary	25.00 F	*- F
23	1		*GRILLE RADIATOR	Not Necessary	165.00 F	*- F
24	1		*GRILLE SUB-ASSY	Not Necessary	335.60 F	*- F
25	1		*WHEEL DISC FRONT	Not Necessary	1,555.10 F	*- F
26	1		*TYRE	Not Necessary	126.74 F	*- F
27	1		*END SET ,TIE ROD RH	Not Necessary	155.90 F	*- F
28	1		*LINER ,FR FENDER ,RH	Not Necessary	198.40 F	*- F
29	1		*PAD FR WHEEL RH	Not Necessary	57.70 F	*- F
30	1		*COVER OUTER MIRROR RH	Not Necessary	89.50 F	*- F
31	1		*MIRROR ASSY ,OUTER REAR VIEW RH	Not Necessary	1,373.50 F	*- F
32	1		*LINER ,FR FENDER LH	Not Necessary	194.30 F	*- F
33	1		*PAD FR WHEEL LH	Not Necessary	57.70 F	*- F
34	1		*PILLAR ,CENTER BODY OUTER LH	Not Necessary	313.40 F	*- F
35	1		*COVER FRONT FLOOR UNDER LH	Not Necessary	425.50 F	*- F
36	1		*COVER FRONT FLOOR UNDER RH	Not Necessary	427.30 F	*- F
37	1		*COVER ASSY ,CENTER FLOOR UNDER LH	Not Necessary	390.20 F	*- F
38	1		*COVER REAR FLOOR UNDER RH	Not Necessary	169.50 F	*- F
39	1		*GARNISH ,REAR SEAT SIDE ,LH	Not Necessary	234.30 F	*- F
40	1		*SOLAR FILM (SIDE WINDOW GLASS)	Not Necessary	125.00 F	*- F
41	1		*FOR SOLAR FILM	Not Necessary	125.00 F	*- F
42	1		*REINFORCEMENT SUB-ASSY ,ROCKER PANEL LH	Repair	332.30 F	*- F
43	1		*PANEL QUARTER WHEEL HOUSE OUTER LH	Repair	286.80 F	*- F
44	1		*PANEL QUARTER WHEEL HOUSE INNER LH	Repair	527.00 F	*- F
45	1		*MOULDING ASSY ,BODY ROCKER PANEL LH	Repair	576.00 F	*- F
46	1		*HINGE ASSY REAR DOOR UPPER LH	*Check	83.30 F	*- F
47	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	*Check	73.30 F	*- F
48	1		*DOOR REAR MOTOR ASSY POWER WINDOW REGULATOR LH	*Check	768.60 F	*- F
49	1		*DOOR REAR WINDOW REGULATOR SUB-ASSY LH	*Check	200.70 F	*- F
50	1		*CHECK ASSY REAR DOOR	*Check	153.50 F	*- F
51	1		*COVER REAR DOOR SERVICE HOLE NO.2 LH	*Check	20.40 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*GLASS SUB ASSY ,REAR DOOR ,LH	*Check	397.80 F	*- F
53	1		*GLASS REAR DOOR QUARTER WINDOW LH	*Check	104.60 F	*- F
54	1		*RUN ,REAR DOOR GLASS ,LH	*Check	118.70 F	*- F
55	1		*DOOR OUTER HANDLE REAR LH	*Check	93.90 F	*- F
56	1		*DOOR LOCK REAR LH	*Check	544.70 F	*- F
57	1		*DOOR REAR LOCK COVER	*Check	8.90 F	*- F
58	2		*REAR DOOR SPEAKER ASSY ,RADIO RH & LH	*Check	985.70 F	*- F
59	2		*PATCH ,SIDE PANEL REAR END RH & LH	*Check	33.70 F	*- F
60	2		*ABSORBER SET ,SHOCK REAR RH & LH	*Check	116.80 F	*- F
61	1		*ARM ASSY UPPER CONTROL REAR LH	*Check	352.40 F	*- F
62	1		*CARRIER SUB-ASSY REAR AXLE LH	*Check	802.70 F	*- F
63	1		*ARM ASSY ,TREAILING REAR LH	*Check	239.70 F	*- F
64	1		*COVER SUB-ASSY ,REAR QUARTER PILLAR LH	*Check	201.30 F	*- F
65	1		*END PANEL SUB-ASSY ,BODY LOWER BACK	*Check	629.80 F	*- F
66	1		*SEAT BELT ASSY REAR SEAT RH	*Check	828.20 F	*- F
67	1		*SEAT BELT ASSY ,REAR SEAT ,LH	*Check	838.20 F	*- F
68	1		*TANK SUB-ASSY FUEL	*Check	850.00 F	*- F
69	1		*PROTECTOR ,FUEL TANK	*Check	295.10 F	*- F
70	1		*REAR MEMBER SUB-ASSY ,RR	*Check	2,171.70 F	*- F
71	1		*COVER ASSY ,ENGINE	*Check	180.10 F	*- F
72	1		*SET COVER ASSY ,ENGINE UNDER CENTER	*Check	452.80 F	*- F
73	1		*COVER ,ENGINE UNDER CENTER	*Check	94.50 F	*- F
74	1		*COVER ENGINE UNDER REAR	*Check	36.50 F	*- F
75	1		*CAP SUB-ASSY WHEEL	*Check	175.80 F	*- F
76	2		*HUB & BEARING ASSY LH & RH	*Check	554.20 F	*- F
77	1		*LOWER ARM SUB-ASSY ,FRONT RH	*Check	631.60 F	*- F
78	1		*KNUCKLE STEERING RH	*Check	555.20 F	*- F
79	1		*WEATHERSTRIP REAR DOOR OPENING TRIM LH	*Check	283.60 F	*- F
80	1		*PANEL ASSY DECK TRIM SIDE ,LH	*Check	344.70 F	*- F
81	1		*BUCKLE SEAT BELT ASSY ,REAR SEAT ,RH	*Check	125.20 F	*- F
82	1		*BUCKLE SEAT BELT ASSY ,REAR SEAT ,CENTER & LH	*Check	208.00 F	*- F
83	1		*MOULDING FRONT DOOR WINDOW FRAME REAR LH	*Check	54.70 F	*- F
84	1		*MOULDING REAR DOOR WINDOW FRAME, FRONT LH	*Check	54.70 F	*- F
85	1		*LID ASSY ,FUEL FILLER OPENING	*Check	164.10 F	*- F
86	1		*LOCK ASSY FUEL LID W/MOTOR	*Check	315.20 F	*- F
87	1		*TUBE FUEL MAIN	*Check	64.40 F	*- F
88	1		*TUBE FUEL TANK TO CANISTER	*Check	145.90 F	*- F
89	1		*SUPPORT FUEL TUBE GROMMET NO.1	*Check	43.30 F	*- F

F=Franchise part.

Total Parts (S\$) 37,491.48 7,462.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,183.00	1,000.00
2	SPRAY PAINT	New	2,772.00	700.00
3	TO REMOVE & REFIT FUEL TANK	New	240.00	60.00
4	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	0.00
5	TO REMOVE AND REFIT REAR CROSSMEMBER	New	200.00	0.00
6	TO REMOVE & REFIT ROOF LINING	New	350.00	100.00
7	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
8	TO RMEOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	240.00	0.00
9	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
10	TO CHECK & RESET SYSTEM FUNCTION	New	250.00	80.00
11	TO REMOVE AND REFIX AIR BAG SYSTEM	New	120.00	80.00
12	TO REMOVE AND REFIX UNDERCARRIAGE	New	200.00	150.00
13	TO APPLY RUST PROOFING ON AFFECTED AREA	New	200.00	60.00
14	TO REPLACE SUNDRY PARTS	New	100.00	0.00
15	TO DO ALIGNMENT /TYRE BALANCING	New	120.00	0.00
16	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
17	TO WASH AND VACUUM	New	60.00	0.00
18	TOWING CHARGE	New	210.00	150.00
Gross Labour Cost (\$\$)			6,685.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >