

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|------------------------------|--|---|----------------|-------|-------------------------|--|
| | SOMPO INSURAN | CE SINGAPORE PL | | Ref: | CS3/SMO22000234/Utf3e2 | |
| | 50 RAFFLES PLAC TOWER SINGAPO | CE #03-03 SINGAPORE LAND DRE 048623 | | Date: | 25/01/2022 | |
| | | | | Code: | SMO | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SJM 5896L | Veh. Inspected | ł | SJL 7174D | |
| | Policy No. | D21MTPV01000965 | Coverage (\$) | | 0.00 | |
| | Claim No. | CMTD2200047/GPL | Excess (\$) | | 0.00 | |
| | Assign From | GRACE TEO | Assign Date | | 07/01/2022 | |
| 2. | Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA STREAM (A) | c.c | | 1799 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2008 | |
| | Chassis No. | RN61086013 | Colour | | BROWN | |
| | Odometer | 301670 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/55 R16 | LAUFENN | | 6 mm | |
| | L/H Front Tyre | 205/55 R16 | LAUFENN | | 6 mm | |
| | R/H Rear Tyre | 205/55 R16 | GITI | | 6 mm | |
| | L/H Rear Tyre | 205/55 R16 | GITI | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUS | IICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 03/01/2022 | Inspect Date / | Time | 07/01/2022 (04:35 PM) | |
| | Survey held at | JCM RENTAL PTE LTD | | | | |
| | 1 BUKIT BATOK CRESCENT #02-03 WCEGA PLAZA SINGAPORE 658064 | | | | | |
| 5a. | Remarks | | | | | |
| | B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000 | | | | |
| 5b. Estimate Days of Repair | | | | | | |
| | ESTIMATED NORI | ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days | | | | |

Report Ref No. CS3/SMO22000234/Utf3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser