

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000236/UGA3Q2**Date:** 08/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900141871-01
Claimant Vehicle No :	SMS8104C	Insured Vehicle No :	SMN3130K
Date of Loss:	06/01/2022	Nature of Claim:	TP
		Claim No:	5004785751SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS8104C		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Standard (AUTO) (2WD) (A)	Engine No:	1ZR0F20005
Reg. Date:	16/03/2020 (Man. Year: 2020)	Chassis No:	MR2BE3BE800007971
Colour:	White	Odometer:	26602 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,841.47	2,285.35	2,556.12	52.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,520.00	1,430.00	48.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,791.47	3,805.35	3,986.12	51.16
+ GST 7.00/7.00% (S\$)	545.40	266.37	279.03	51.16
Nett Amount (S\$)	8,336.87	4,071.72	4,265.15	51.16
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		107.00		
	Nett Liability (S\$)	4,822.72		

INSPECTION

Date of Assignment:	07/01/2022		
Date Inspected:	07/01/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	531.10 FL	*531.10 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	116.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	221.00 FL	*- FL
4	2		*REAR BUMPER SIDE HOLDER	Not Necessary	122.00 FL	*- FL
5	8		*REAR BUMPER CLIPS	Necessary	34.40 FL	*34.40 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 FL	*395.00 FL
7	1		*REAR END PANEL	Repair	590.00 FL	*- FL
8	1		*REAR END PANEL INNER GARNISH	Twisted	240.00 FL	*240.00 FL
9	1		*BOOTLID	Dented	856.40 FL	*856.40 FL
10	1		*BOOTLID INNER LOCK	Serviceable	382.50 FL	*- FL
11	1		*BOOTLID RUBBER	Twisted	185.00 FL	*185.00 FL
12	1		*BOOTLID COROLLA BADGE	Necessary	48.00 FL	*48.00 FL
13	1		*BOOTLID ALTIS BADGE	Necessary	44.00 FL	*44.00 FL
14	2		*BOOTLID REFLECTOR	Not Necessary	680.00 FL	*- FL
15	2		*REAR LAMPS	Serviceable	990.00 FL	*- FL
16	2		*TAIL LAMP BLACK GARNISH	Cut	84.00 FL	*84.00 FL
17	1		*REAR LUGGAGE FLOOR PANEL FLOORBOARD	Torn	267.50 FL	*267.50 FL
18	1		*BOOTLID CENTRE EMBLEM	Necessary	68.40 FL	*68.40 FL
19	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*220.00 FS
					Sub Total (\$\$)	6,305.30 2,973.80
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,463.83 688.45
					Total Parts (\$\$)	4,841.47 2,285.35

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	250.00	40.00
2	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	120.00	60.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ADJUST AND REALIGN THE SAME	New	1,200.00	600.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	750.00
Gross Labour Cost (\$\$)			2,950.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >