



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 1642Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FRONT FORK TUBE ASSY (CONSISTENT)	SERVICEABLE	640.00	-
1	FORK UNDER BRACKET (CONSISTENT)	SERVICEABLE	185.00	-
1	HANDLE-BAR (CONSISTENT)	SERVICEABLE	105.00	-
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	55.00	-
1	HANDLE BAR ENDS O/S (CONSISTENT)	CUT	78.00	30.00
2	SIDE MIRRORS (CONSISTENT)	O/S CUT	110.00	55.00
1	FRONT PILOT LIGHT (CONSISTENT)	CRACKED	228.00	228.00
2	FRONT SIGNALS (CONSISTENT)	O/S BROKEN / MISSING	140.00	60.00
1	FRONT SIGNAL LOWER GARNISH (CONSISTENT)	MISSING	95.00	95.00
1	FRONT INNER COVER (CONSISTENT)	CRACKED	180.00	145.00
1	SET FAIRING ASSY (CONSISTENT)	BROKEN	625.00	520.00
1	FRONT FOOTREST BRACKETS (CONSISTENT)	BENT	65.00	65.00
2	FRONT FOOTREST (CONSISTENT)	O/S CUT	84.00	42.00
1	BRAKE PEDAL (CONSISTENT)	BENT	42.00	42.00
2	REAR FOOTREST (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR FOOTREST BRACKET O/S (CONSISTENT)	CRACKED	156.00	112.00
1	EXHAUST ASSY (CONSISTENT)	BENT / TWISTED	528.00	528.00
1	EXHAUST PROTECTOR (CONSISTENT)	GRAZED	60.00	60.00
1	EXHAUST PROTECTOR END CAP (CONSISTENT)	DISTORTED	45.00	35.00
1	REAR FENDER - 1 (CONSISTENT)	NOT NECESSARY	95.00	-
1	REAR FENDER - 2 (CONSISTENT)	DEFORMED	68.00	68.00
2	REAR FENDER BRACKET (CONSISTENT)	BENT (1PC ONLY)	106.00	53.00
2	REAR SIGNAL (CONSISTENT)	O/S CUT	180.00	60.00
1	BRAKE PUMP (CONSISTENT)	SERVICEABLE	198.00	-
1	REAR NUMBER PLATE LAMP (CONSISTENT)	BROKEN	98.00	68.00
1	REAR RIM (CONSISTENT)	TO REPAIR SEE LABOUR	350.00	-
1	REAR RIM SHAFT (CONSISTENT)	NOT NECESSARY	98.00	-
1	SWING ARM (CONSISTENT)	NOT NECESSARY	380.00	-
1	SWING ARM BUSH (CONSISTENT)	NOT NECESSARY	180.00	-

Report Ref No. CC4/ASM22000249/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SWING ARM SHAFT (CONSISTENT)	NOT NECESSARY	98.00	-
	LESS 10% DISCOUNT		-535.20	-226.60
			4,816.80	2,039.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN) (CONSISTENT)	BENT	38.00	20.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	95.00	-
1	HELMET (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	180.00	-
1	SET STICKER (SN) (CONSISTENT)	NECESSARY	95.00	68.00
			494.00	88.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REALIGN BODY FRAME.	NOT NECESSARY	380.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF REAR RIM AND HELMET.		480.00	300.00
			940.00	300.00
GRAND TOTAL			6,250.80	2,427.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CC4/ASM22000249/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.