

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0011/22

DATE : 04-JAN-2022

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : M/S ASIATIC GREEN HORTICULTURE AND LANDSCAPE
ADDRESS : 84 SUNGEI TENGAH ROAD

S(698986)

TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 7210048100

VEHICLE NO : GBL3195P

MODEL CODE : YDTARCBM20ED2Y597Z

MODEL/YEAR : NISSAN NV200 PETROL - AT MY2020

ENGINE NO : HR16179366D

CHASSIS NO : JN1YAAM20Z0001459

MILEAGE : 19030 KM

DATE IN : 04/01/2022

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 01/01/2022

- 9645 0084 e/mur@tanchoy.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBL3195P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR,LH INNER REAR FENDER PANEL,LH INNER RR FENDER EXTENSION PANEL	3675.00	
2	ZZ/002	LH INNER WHEELHOUSE,RENEW LH RR FENDER OUTER PANEL OUTER END PANEL,RR BUMPER AND TAIL GATE		
3	ZZ/003	CHARGES TO SPRAY PAINTING FOR THE ABOVE MENTIONED PANEL	1800.00	
4	ZZ/004	PERFORM RUSTPROOFING TRUNKFLOOR,OUTER END PANEL LH RR FENDER OUTER PANEL	360.00	
5	ZZ/005	REMOVE AND INSTALL REAR WINDSCREEN GLASS	180.00	
6	ZZ/006	REMOVE AND TRANSFER TAIL GATE MECHANISM	80.00	
7	ZZ/007	RENEW REVERSE SENSOR	55.00	
8	ZZ/008	APPLY SEALANT TO OUTER END PANEL AND TAIL GATE	200.00	
9	ZZ/009	PERFORM WHEEL ALIGNMENT	95.00	
10	ZZ/011	COMPUTER CHECK DIAGNOSIS	120.00	
11	ZZ/10	RENEW LH RR COMB LAMP AND CHECK REAR WIRING SYSTEM	48.00	
		TOTAL LABOUR CHARGES	6613.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBL3195P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	LH RR COMB LAMP	26555-JX53A	252.00		
2	SENSOR-REVERSE	SENSOR			250.00
3	EMBLEM-REAR VANETTE	90892-JX00A	64.90		
4	EMBLEM-REAR NV200	90895-JX00A	94.40		
5	EMBLEM-REAR NISSAN	90890-JX00A	64.90		
6	REAR LICENCE PLATE	RLP			60.00
7	LABEL-PAX6	PAX			15.00
8	70KM/H STICKER	70KM/H			15.00
9	OUTER RR END PANEL	75617-JX00A	115.20		
10	LH SIDE BRACKET RR BUMPER	85229-JX00A	37.20		
11	ENERGY ABSORBER RR BUMPER	85090-JX00A	94.00		
12	REAR BUMPER	85022-5LA0B	915.60		
13	RH TAILGATE LOCK COVER	90595-JX00A	3.30		
14	RH TAILGATE LOCK COVER	90594-JX00A	3.30		
15	TAILGATE LOCK	90500-5LA0A	287.10		
16	STRIKER-TAIL GATE	90570-5LA0A	34.80		
17	REAR W/SCREEN SEALANT	SEALANT - 4			80.00
18	LH BACKDOOR STAY	90451-JX00A	200.00		
19	WEATHER STRIP TAILGATE	90830-5LA0A	88.40		
20	TAILGATE	K010M-JX0AB	1635.00		
21	LH RAILGUIDE FINISHER	76827-JX00A	58.50		
22	LH RR FENDER RAIL GUIDE	77761-JX00A	167.30		
23	LH RR FENDER BACK PILLAR OUTER PANEL	77611-JX00A	423.00		
24	LH RR FENDER OUTER PANEL	78101-3LR0B	1439.70		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBL3195P

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
SUB TOTAL			5978.60	0.00	420.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1195.72	0.00	0.00	
GRAND TOTAL			4782.88	0.00	420.00	
OVERALL TOTAL			5202.88			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBL3195P

TOTAL LABOUR CHARGES	6613.00
TOTAL SPARE PARTS CHARGES	5202.88

GRAND TOTAL	11815.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.