

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0011/22

DATE : 04-JAN-2022

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : M/S ASIATIC GREEN HORTICULTURE AND LANDSCAPE
ADDRESS : 84 SUNGEI TENGAH ROAD

S(698986)

TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 7210048100

VEHICLE NO : GBL3195P

MODEL CODE : YDTARCBM20ED2Y597Z

MODEL/YEAR : NISSAN NV200 PETROL - AT MY2020

ENGINE NO : HR16179366D

CHASSIS NO : JN1YAAM20Z0001459

MILEAGE : 19030 KM

DATE IN : 04/01/2022

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 01/01/2022

not Authorized
LHM
11/1/22
take photo before painting
11 days

P/P \$ 10888.76

- 9645 0084 e/mur@tanchoy.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBL3195P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S
			CHARGES	RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR,LH INNER REAR FENDER PANEL,LH INNER RR FENDER EXTENSION PANEL	3675.00	3510
2	ZZ/002	LH INNER WHEELHOUSE,RENEW LH RR FENDER OUTER PANEL OUTER END PANEL,RR BUMPER AND TAIL GATE		
3	ZZ/003	CHARGES TO SPRAY PAINTING FOR THE ABOVE MENTIONED PANEL	1800.00	1500
4	ZZ/004	PERFORM RUSTPROOFING TRUNKFLOOR,OUTER END PANEL LH RR FENDER OUTER PANEL	360.00	240
5	ZZ/005	REMOVE AND INSTALL REAR WINDSCREEN GLASS	180.00	✓
6	ZZ/006	REMOVE AND TRANSFER TAIL GATE MECHANISM	80.00	✓
7	ZZ/007	RENEW REVERSE SENSOR	55.00	✓
8	ZZ/008	APPLY SEALANT TO OUTER END PANEL AND TAIL GATE	200.00	✓
9	ZZ/009	PERFORM WHEEL ALIGNMENT	95.00	X
10	ZZ/011	COMPUTER CHECK DIAGNOSIS	120.00	✓
11	ZZ/10	RENEW LH RR COMB LAMP AND CHECK REAR WIRING SYSTEM	48.00	✓
TOTAL LABOUR CHARGES			6613.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBL3195P

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	LH RR COMB LAMP	26555-JX53A <i>cue</i>	252.00	<i>✓</i>
2	SENSOR-REVERSE	SENSOR <i>✓</i>	<i>shold</i>	250.00 <i>✓</i>
3	EMBLEM-REAR VANETTE	90892-JX00A <i>nei</i>	64.90	<i>✓</i>
4	EMBLEM-REAR NV200	90895-JX00A <i>nei</i>	94.40	<i>✓</i>
5	EMBLEM-REAR NISSAN	90890-JX00A <i>nei</i>	64.90	<i>✓</i>
6	REAR LICENCE PLATE	RLP	<i>su</i>	60.00 <i>x</i>
7	LABEL-PAX6	PAX <i>✓</i>	<i>nu</i>	15.00 <i>✓</i>
8	70KM/H STICKER	70KM/H <i>✓</i>	<i>nu</i>	15.00 <i>✓</i>
9	OUTER RR END PANEL	75617-JX00A <i>DD</i>	115.20	<i>✓</i>
10	LH SIDE BRACKET RR BUMPER	85229-JX00A <i>sent</i>	37.20	<i>✓</i>
11	ENERGY ABSORBER RR BUMPER	85090-JX00A <i>2000</i>	94.00	<i>2 ✓</i>
12	REAR BUMPER	85022-5LA0B <i>DIS</i>	915.60	<i>✓</i>
13	RH TAILGATE LOCK COVER	90595-JX00A <i>17</i>	3.30	<i>x</i>
14	RH TAILGATE LOCK COVER	90594-JX00A <i>m</i>	3.30	<i>x</i>
15	TAILGATE LOCK	90500-5LA0A <i>jm</i>	287.10	<i>✓</i>
16	STRIKER-TAIL GATE	90570-5LA0A <i>17</i>	34.80	<i>x</i>
17	REAR W/SCREEN SEALANT	SEALANT - 4 <i>✓</i>	<i>nei</i>	80.00 <i>✓</i>
18	LH BACKDOOR STAY	90451-JX00A <i>17</i>	200.00	<i>x</i>
19	WEATHER STRIP TAILGATE	90830-5LA0A <i>7m</i>	88.40	<i>2 ✓</i>
20	TAILGATE	K010M-JX0AB <i>3.600</i>	1635.00	<i>✓</i>
21	LH RAILGUIDE FINISHER	76827-JX00A <i>17</i>	58.50	<i>x</i>
22	LH RR FENDER RAIL GUIDE	77761-JX00A <i>17</i>	167.30	<i>x</i>
23	LH RR FENDER BACK PILLAR OUTER PANEL	77611-JX00A <i>R</i>	423.00	<i>x</i>
24	LH RR FENDER OUTER PANEL	78101-3LR0B <i>346</i>	1439.70	<i>✓</i>

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBL3195P

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		5978.60	0.00	420.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1195.72	0.00	0.00
GRAND TOTAL		4782.88	0.00	420.00
OVERALL TOTAL		5202.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBL3195P

TOTAL LABOUR CHARGES	6613.00
TOTAL SPARE PARTS CHARGES	5202.88

GRAND TOTAL	11815.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBL3195P

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	CLIP-PLATE LUGGAGE REAR GARNISH@SGD\$2.30 EACH <i>ADD</i>	01553-05793 <i>new</i>	11.50	✓		OK
2	INNER RR END PANEL <i>ADD</i>	75614-JX00A <i>body</i>	576.00	✓		OK
3	PLATE-LUGGAGE REAR GARNISH <i>ADD</i>	84992-JX00A <i>body</i>	68.80	✓		OK
4	LH RR COMB LAMP	26555-JX53A	252.00			OK ✓
5	SENSOR-REVERSE	SENSOR			250.00	OK ✓
6	EMBLEM-REAR VANETTE	90892-JX00A	64.90			OK ✓
7	EMBLEM-REAR NV200	90895-JX00A	94.40			OK ✓
8	EMBLEM-REAR NISSAN	90890-JX00A	64.90			OK ✓
9	LABEL-PAX6	PAX			15.00	OK ✓
10	70KM/H STICKER	70KM/H			15.00	OK ✓
11	OUTER RR END PANEL	75617-JX00A	115.20			OK ✓
12	LH SIDE BRACKET RR BUMPER	85229-JX00A	37.20			OK ✓
13	ENERGY ABSORBER RR BUMPER	85090-JX00A	94.00			OK ✓
14	REAR BUMPER	05022-5LACB	915.60			OK ✓
15	TAILGATE LOCK	90500-5LAQA	287.10			OK ✓
16	REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK ✓
17	WEATHER STRIP TAILGATE	90830-5LACA	88.40			OK ✓
18	TAILGATE	K010M-JX0AB	1635.00			OK
19	LH RR FENDER OUTER PANEL	78101-3LR0B	1439.70			OK
SUB TOTAL			5744.70	0.00	360.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1148.94	0.00	0.00	
GRAND TOTAL			4595.76	0.00	360.00	
OVERALL TOTAL			4955.76			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED