

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22000253/KEA3Q2**Date:** 31/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100455388
Claimant Vehicle No :	SHD9299E	Insured Vehicle No :	SLA5928T
Date of Loss:	04/01/2022	Nature of Claim:	TP
		Claim No:	2423428761SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9299E		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2C08754
Reg. Date:	17/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU803079981
Colour:	Metallic Pearl White/Red	Odometer:	339435 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 3 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,968.42	2,310.05	4,658.37	66.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	1,860.00	2,930.00	61.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,758.42	4,170.05	7,588.37	64.54
+ GST 7.00/7.00% (S\$)	823.09	291.90	531.19	64.54
Nett Amount (S\$)	12,581.51	4,461.95	8,119.56	64.54
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
+ Car Rental (10.0 x S\$112.35/day) (S\$)		1,123.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,092.90		
Global Sum Settlement (S\$)		6,090.00		

INSPECTION

Date of Assignment:	06/01/2022	
Date Inspected:	06/01/2022	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR RH	Repair	1,300.70 FL	*- FL
2	1		*FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE RH	Serviceable	193.50 FL	*- FL
3	1		*HANDLE ASSY ,FRONT DOOR OUTSIDE RH	Serviceable	390.60 FL	*- FL
4	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Repair	110.60 FL	*- FL
5	1		*HINGE ASSY ,FRONT DOOR ,UPPER RH	Repair	97.50 FL	*- FL
6	1		*TAPE BLACK OUT ,NO.1 FRT RH	Not Necessary	13.30 FL	*- FL
7	1		*TAPE BLACK OUT ,NO.2 FRT RH	Not Necessary	43.50 FL	*- FL
8	1		*TAPE BLACK OUT ,NO.3 FRT RH	Not Necessary	26.30 FL	*- FL
9	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT RH	Serviceable	926.00 FL	*- FL
10	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW RH	Serviceable	238.30 FL	*- FL
11	1		*WEATHERSTRIP ,FRONT DOOR ,RH	Serviceable	231.30 FL	*- FL
12	1		*PANEL SUB-ASSY ,REAR DOOR ,RH	Bent	1,294.90 FL	*1,294.90 FL
13	1		*HANDLE ASSY ,REAR DOOR OUTSIDE ,RH	Serviceable	97.40 FL	*- FL
14	1		*FRAME SUB-ASSY ,REAR DOOR OUTSIDE HANDLE RH	Serviceable	193.50 FL	*- FL
15	1		*HINGE ASSY ,REAR DOOR ,LOWER RH	Repair	87.10 FL	*- FL
16	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Repair	98.90 FL	*- FL
17	1		*TAPE ,BLACK OUT ,NO.1 REAR RH	Necessary	21.90 FL	*21.90 FL
18	1		*TAPE ,BLACK OUT ,NO.2 REAR RH	Necessary	34.90 FL	*34.90 FL
19	1		*TAPE ,BLACK OUT ,NO.3 REAR RH	Necessary	15.40 FL	*15.40 FL
20	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,REAR RH	Serviceable	926.00 FL	*- FL
21	1		*REGULATOR SUB-ASSY, REAR DOOR WINDOW ,RH	Serviceable	206.70 FL	*- FL
22	1		*WEATHERSTRIP ,REAR DOOR ,RH	Serviceable	180.10 FL	*- FL
23	1		*PANEL SUB-ASSY ,QUARTER ,RH	Bent	871.50 FL	*871.50 FL
24	1		*LINER ,REAR WHEEL HOUSE ,RH	Serviceable	139.80 FL	*- FL
25	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Cracked	594.80 FL	*594.80 FL
26	1		*REINFORCEMENT SUB-ASSY ,ROCKER PANEL ETC	Repair	343.40 FL	*- FL
27	1		*CLIP (FOR FRONT DOOR TRIM BOARD)	Not Necessary	65.00 FS	*- FS
28	1		*CLIP (FOR REAR DOOR TRIM BOARD)	Not Necessary	65.00 FS	*- FS
29	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
30	1		*FRT DOOR STICKER TRANSCAB	Necessary	100.00 FS	*60.00 FS
31	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
32	1		*ROCKER PANEL CLIP	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,137.90	3,018.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,169.48	708.35
Total Parts (\$\$)	6,968.42	2,310.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	60.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	880.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	100.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,800.00	800.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			4,790.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >