

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000254/ATCN2**Date:** 23/03/2022**REFERENCE**

Insured/Claimant: KOH GUEK HONG (XU YUEFENG) Policy No: 2070177540
Date of Loss: 06/12/2021 Nature of Claim: OD Claim No: 0711184211SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBG383J**
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZDC21288
Reg. Date: 28/12/2020 (Man. Year: 2020) Chassis No: WAUZZZF33M1050133
Colour: White Odometer: 12165 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$150,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65R17 Rear Tyre Size: 215/65R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,285.00	3,880.72	7,404.28	65.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,952.00	2,922.00	16,030.00	84.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,237.00	6,802.72	23,434.28	77.50
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	29,437.00	6,002.72	23,434.28	79.61
+ GST 7.00/7.00% (S\$)	2,060.59	420.19	1,640.40	79.61
Nett Amount (S\$)	31,497.59	6,422.91	25,074.68	79.61

INSPECTION

Date of Assignment: 10/01/2022
Date Inspected: 07/01/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER-LH	Repair	3,388.00 FS	*- FS
2	1		*QUARTER WINDOW-LH	Not Necessary	614.00 FS	*- FS
3	1		*REAR END PANEL	Not Necessary	311.00 FS	*- FS
4	1		*PRIMER	Not Necessary	20.00 FS	*- FS
5	1		*TAIL LIGHT-LH	Cut	926.00 FS	*740.40 FS
6	1		*TAIL LIGHT TRIM-LH	Not Necessary	30.00 FS	*- FS
7	1		*REAR DOOR-LH	Dented	2,909.00 FS	*2,327.20 FS
8	1		*REAR DOOR OUTER SEAL-LH	Necessary	135.00 FS	*108.00 FS
9	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	311.00 FS	*- FS
10	1		*REAR DOOR CATCH-LH	Damaged	120.00 FS	*96.00 FS
11	1		*REAR DOOR HANDLE-LH	Cut	198.00 FS	*158.00 FS
12	1		*REAR DOOR HOUSING-LH	Cut	27.00 FS	*21.60 FS
13	2		*REAR DOOR UNDERLAY-FRONT/BACK-LH	Not Necessary	9.00 FS	*- FS
14	1		*REAR DOOR MOUNTING BAR	Not Necessary	162.00 FS	*- FS
15	1		*REAR DOOR BOWDEN CABLE	Not Necessary	52.00 FS	*- FS
16	1		*REAR DOOR COVER-LH	Necessary	257.00 FS	*205.20 FS
17	1		*REAR WHEEL ARCH COVER-LH/RH	N/s Necessary	536.00 FS	*214.40 FS
18	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
19	1		*ARYLIC SEALANT	Not Necessary	180.00 FS	*- FS
20	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
21	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
22	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*SUNDRIES	Necessary	400.00 FS	*9.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **11,285.00** **3,880.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	0.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
3	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
4	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	300.00	0.00
5	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS	New	400.00	0.00
6	TO CARRY OUT WATER SEEPAGE TEST ON REAR 1/4 GLASS	New	200.00	0.00
7	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	400.00	280.00
8	TO DISMANTLE AND REINSTALL REAR BUMPER.TO RENEW LHS REAR DOOR.CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING.RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	8,800.00	1,250.00
9	TO RESPRAY LHS REAR FENDER,LHS REAR DOOR,DOOR HANDLE,LHS SILL PANEL,ROOF CHANNEL.DOOR ENTRANCES,DRAIN CHANNEL AND REAR END PANELLING	New	5,500.00	1,200.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			18,952.00	2,922.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >